

REF: C88/CTI 21008578/DVL

ASSIGNMENT

Insured: GBJ 7376T
 Policy No: DMCVSNW00080092102
 Claim No: SNM21D204510/C02/TANKW
 Sum Insured: _____ Excess: _____
 (Officer's Record)
 Make of Veh: _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. of Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / TR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PC 7379G Yr Regn: May 2018
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Mini bus
 Make: Toyota Hiace Commuter cc 2982
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 52704 T/Radio: Insured / Std / NI / NA
 Eng/No: 1KD2764312
 C/No: KDH12230034739
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 195/80 R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Dunlop
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 11/08/2021 D.O.L: 18/08/2021
 Survey held at Serve You AMK
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Chine Taping GBS 7376T</u>
	<u>Re bumper new tailgate rear end panel</u>
<u>22/9/21 PRS</u>	<u>Repair range 3K to 3.5K with 4 days for rep</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 22/9/21-typist

Report Format: PRS

Lump Sum / L.B.R (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others