

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21008581/EGA3Q2**Date:** 17/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800151552
Claimant Vehicle No :	SMT2199M	Insured Vehicle No :	SMF8688C
Date of Loss:	15/08/2021	Nature of Claim:	TP
		Claim No:	7075577289SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT2199M		
Make & Model:	VOLKSWAGEN TOURAN, 1.4 1.4 TSI CL 5T13NZ (A)	Engine No:	CZDA71423
Reg. Date:	31/03/2020 (Man. Year: 2019)	Chassis No:	WVGZZZ1TZLW011859
Colour:	Blue	Odometer:	17346 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,620.51	5,872.86	1,747.65	22.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,060.00	8,840.00	3,220.00	26.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,680.51	14,712.86	4,967.65	25.24
+ GST 7.00/7.00% (S\$)	1,377.64	1,029.90	347.74	25.24
Nett Amount (S\$)	21,058.15	15,742.76	5,315.39	25.24
+ Car Rental (14.0 x S\$100.00/day + 7.00% GST) (S\$)		1,498.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		96.00		
Nett Liability (S\$)		17,338.76		

INSPECTION

Date of Assignment:	16/08/2021		
Date Inspected:	18/08/2021	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	12.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*DOOR LHS REAR DOOR	Dented	2,436.42 FS	*2,436.42 FS
2	1	*DOOR SEAL OUTER BLACK	Bent	219.54 FS	*219.54 FS
3	1	*SOUND ABSORBER LAMINATED DOOR INSULATOR	Necessary	43.65 FS	*43.65 FS
4	1	*DOOR HINGE HALF LOWER PAR DOOR HINGE UPPER (LOWER)	Necessary	45.17 FS	*45.17 FS
5	1	*DOOR HINGE HALF UPPER PAR DOOR HINGE UPPER (UPPER)	Not Necessary	74.50 FS	*- FS
6	1	*DOOR HINGE HALF LOWER PAR DOOR HINGE LOWER (LOWER)	Not Necessary	45.17 FS	*- FS
7	1	*DOOR HINGE HALF UPPER PAR DOOR HINGE LOWER (UPPER)	Not Necessary	44.96 FS	*- FS
8	2	*BOLT WITH POLYGON SOCKET	Necessary	10.34 FS	*10.34 FS
9	4	*HEX BOLT WITH INTERNAL TO	Necessary	14.36 FS	*14.36 FS
10	1	*DOOR LATCH DOOR LOCK	Not Necessary	419.61 FS	*- FS
11	2	*FILL HD SCREW	Necessary	5.52 FS	*5.52 FS
12	1	*WINDOW REGULATOR WITHOUT	Not Necessary	362.24 FS	*- FS
13	1	*DOOR TRIM PANEL LHR DOOR BOARD	Not Necessary	801.17 FS	*- FS
14	1	*SECTIONAL PART SIDE PANEL LHR FENDER	Dented	1,774.72 FS	*1,774.72 FS
15	1	*2K-FULLSCHAUM	Necessary	154.20 FS	*154.20 FS
16	1	*SEALANT CAN BE SPRAYED	Necessary	64.23 FS	*64.23 FS
17	1	*ZINC SPRAY	Necessary	68.87 FS	*68.87 FS
18	1	*2K-BODY ADHESIVE	Necessary	444.39 FS	*444.39 FS
19	1	*SIDE WINDOW NOT PRE -TREAT LHR FENDER GLASS	Necessary	333.64 FS	*333.64 FS
20	1	*1K WINDOW ADHESIVE	Necessary	51.16 FS	*51.16 FS
21	1	*ALL PURPOSE CLEANER	Necessary	97.37 FS	*97.37 FS
22	1	*PRIMER	Necessary	28.44 FS	*28.44 FS
23	1	*ACTIVATOR FOR PRECOATED W	Necessary	26.15 FS	*26.15 FS
24	2	*APPLICATOR	Necessary	20.88 FS	*20.88 FS
25	1	*STONE PROTECTION FOIL STONE LHR FENDER FOIL	Necessary	33.81 FS	*33.81 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 7,620.51 5,872.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	5,040.00	4,200.00
4	SPRAY PAINT	New	3,200.00	1,600.00
5	TRANSFER DOOR MECHANISM	New	840.00	840.00
6	R&R LHR FENDER GLASS	New	840.00	840.00
7	R&R REAR LUGGAGE TRIM	New	840.00	420.00
8	LHR FENDER GLASS	New	180.00	180.00
9	R&R DOOR BOARD LEATHER	New	360.00	0.00
Gross Labour Cost (S\$)			12,060.00	8,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >