



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 3516U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR PANEL TOP (SN)	BENT	1,185.20	1,185.20
1	TOWER TRANSIT LOGO (B)(SN)	NECESSARY	300.00	150.00
1	60KM/HR STICKER (SN)	NOT NECESSARY	3.00	-
			1,488.20	1,335.20
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE:- REAR ENGINE DOOR.		650.00	650.00
	TO PERFORM REPAIR WORKS ON:- .OSR LIGHT POD FIBER BODY GLASS. .LEFT & RIGHT REAR DOME.		1,950.00	650.00
	SPRAY PAINTING:- .REAR ENGINE DOOR. .OSR LIGHT POD FIBER GLASS BODY. .LEFT & RIGHT REAR DOME.		2,560.00	1,920.00
			5,160.00	3,220.00
GRAND TOTAL			6,648.20	4,555.20

RECOMMENDED COST OF REPAIRS			4,555.20
------------------------------------	--	--	-----------------

Report Ref No. CS/SMR21008582/R1uf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.