

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21008591/BQCEN2**Date:** 05/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00059692103

**Claimant Vehicle No :** SLM7501P **Insured Vehicle No :** GBG1822C

Date of Loss: 11/08/2021 Nature of Claim: TP Claim No: SNM21D204484/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLM7501P**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 E (A) Engine No: 2ZR6859424

Reg. Date: 10/04/2017 (Man. Year: 2016) Chassis No: ZVW516034484

Colour: White Odometer: 0 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15

Front Left Side: KAPSEN 5 mm Rear Left Side: KAPSEN 5 mm

Front Right Side: KAPSEN 5 mm Rear Right Side: KAPSEN 5 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 47,612.63         | 25,193.13         | 22,419.50         | 47.09         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 7,300.00          | 4,540.00          | 2,760.00          | 37.81         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>54,912.63</b>  | <b>29,733.13</b>  | <b>25,179.50</b>  | <b>45.85</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>23,750.00</b>  |                   |               |
| <b>(\$\$)</b>                             | 54,912.63         | 23,750.00         | 31,162.63         | 56.75         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 3,843.88          | 1,662.50          | 2,181.38          | 56.75         |
| <b>Nett Amount (\$\$)</b>                 | <b>58,756.51</b>  | <b>25,412.50</b>  | <b>33,344.01</b>  | <b>56.75</b>  |

**INSPECTION**

Date of Assignment: 02/03/2022

Date Inspected: 17/08/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 21.0 days

**Adjuster:** Lim Teow Guan**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                 |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 05 Apr 2022)                   |
| <b>Parts:</b>        | 144                                                                                                                                                                          | TOYOTA PRIUS HYBRID 1.8 E (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                               |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLM7501P)                                                                                                                                    |                                                                 |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                 |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                 |

### Recommended Parts

| No. | Qty | Part No. Particulars                          | Condition     | Repairer's  | Amount       |
|-----|-----|-----------------------------------------------|---------------|-------------|--------------|
| 1   | 1   | *BONNET                                       | Dented        | 938.40 FL   | *869.10 FL   |
| 2   | 1   | *BONNET RH HINGE                              | Bent          | 87.70 FL    | *59.90 FL    |
| 3   | 1   | *BONNET LH HINGE                              | Bent          | 87.70 FL    | *59.90 FL    |
| 4   | 1   | *BONNET LOCK                                  | Jammed        | 151.00 FL   | *85.00 FL    |
| 5   | 1   | *BONNET LOCK CABLE                            | Jammed        | 56.30 FL    | *56.30 FL    |
| 6   | 1   | *BONNET INSULATOR                             | Torn          | 393.30 FL   | *393.30 FL   |
| 7   | 1   | *WIPER GARNISH                                | Broken        | 661.30 FL   | *450.00 FL   |
| 8   | 1   | *WIPER GARNISH RH SIDE COVER                  | Broken        | 28.70 FL    | *28.70 FL    |
| 9   | 1   | *WIPER GARNISH LH SIDE COVER                  | Broken        | 28.70 FL    | *28.70 FL    |
| 10  | 1   | *FRONT WINDSCREEN GLASS                       | Broken        | 1,637.30 FL | *1,637.30 FL |
| 11  | 1   | *FRONT WINDSCREEN GLASS UPPER RUBBER MOULDING | Necessary     | 165.00 FL   | *123.50 FL   |
| 12  | 1   | *FRONT WINDSCREEN GLASS LOWER RUBBER MOULDING | Necessary     | 155.00 FL   | *123.50 FL   |
| 13  | 1   | *FRONT WINDSCREEN GLASS RH SIDE MOULDING      | Necessary     | 157.20 FL   | *123.50 FL   |
| 14  | 1   | *FRONT WINDSCREEN GLASS LH SIDE MOULDING      | Necessary     | 157.20 FL   | *123.50 FL   |
| 15  | 1   | *FRONT BUMPER                                 | Broken        | 781.10 FL   | *781.10 FL   |
| 16  | 1   | *FRONT BUMPER CENTRE LOGO                     | Necessary     | 172.10 FL   | *88.00 FL    |
| 17  | 1   | *FRONT BUMPER LH TOWING COVER                 | Dislodged     | 28.10 FL    | *28.10 FL    |
| 18  | 1   | *FRONT BUMPER RH TOWING COVER                 | Dislodged     | 28.10 FL    | *28.10 FL    |
| 19  | 1   | *FRONT BUMPER UPPER GRILLE                    | Broken        | 331.90 FL   | *331.90 FL   |
| 20  | 1   | *FRONT BUMPER LOWER GRILLE                    | Broken        | 163.40 FL   | *163.40 FL   |
| 21  | 1   | *FRONT BUMPER RH SIDE RETAINER                | Necessary     | 76.90 FL    | *76.90 FL    |
| 22  | 1   | *FRONT BUMPER LH SIDE RETAINER                | Necessary     | 76.90 FL    | *76.90 FL    |
| 23  | 1   | *FRONT BUMPER UPPER REINFORCEMENT             | Not Damaged   | 691.10 FL   | *- FL        |
| 24  | 1   | *FRONT BUMPER UPPER REINFORCEMENT RH STAY     | Not Damaged   | 115.90 FL   | *- FL        |
| 25  | 1   | *FRONT BUMPER UPPER REINFORCEMENT LH STAY     | Not Damaged   | 115.90 FL   | *- FL        |
| 26  | 1   | *FRONT BUMPER LOWER REINFORCEMENT             | Not Damaged   | 236.00 FL   | *- FL        |
| 27  | 1   | *FRONT BUMPER LOWER REINFORCEMENT RH STAY     | Not Damaged   | 98.00 FL    | *- FL        |
| 28  | 1   | *FRONT BUMPER LOWER REINFORCEMENT LH STAY     | Not Damaged   | 98.00 FL    | *- FL        |
| 29  | 1   | *FRONT BUMPER INNER SPONGE                    | Broken        | 169.80 FL   | *72.00 FL    |
| 30  | 1   | *FRONT BUMPER INNER PLASTIC FRAME             | Broken        | 99.80 FL    | *99.80 FL    |
| 31  | 1   | *FRONT BUMPER RH SIDE AIR GUIDE               | Not Damaged   | 61.80 FL    | *- FL        |
| 32  | 1   | *FRONT BUMPER LH SIDE AIR GUIDE               | Broken        | 61.80 FL    | *61.80 FL    |
| 33  | 1   | *FRONT BUMPER LOWER SPLASH SHIELD COVER       | Broken        | 134.60 FL   | *134.60 FL   |
| 34  | 1   | *FRONT BUMPER LH FOG LAMP                     | No such part  | 673.40 FL   | *- FL        |
| 35  | 1   | *FRONT BUMPER RH FOG LAMP                     | No such part  | 673.40 FL   | *- FL        |
| 36  | 1   | *FRONT BUMPER AIR VENT MOTOR                  | No such part  | 204.10 FL   | *- FL        |
| 37  | 1   | *FRONT BUMPER NUMBER PLATE GARNISH            | Broken        | 78.00 FL    | *78.00 FL    |
| 38  | 1   | *FRONT BUMPER UPPER CENTRE RUBBER SEAL        | Not Necessary | 172.40 FL   | *- FL        |
| 39  | 1   | *LH HEADLAMP ASSY                             | Missing       | 3,214.30 FL | *2,721.10 FL |
| 40  | 1   | *LH HEADLAMP PANEL                            | Dented        | 237.00 FL   | *237.00 FL   |
| 41  | 1   | *LH HEADLAMP ECU                              | Missing       | 682.20 FL   | *450.00 FL   |
| 42  | 1   | *RH HEADLAMP ASSY                             | Broken        | 3,213.40 FL | *2,721.10 FL |
| 43  | 1   | *RH HEADLAMP PANEL                            | Not Damaged   | 237.00 FL   | *- FL        |
| 44  | 1   | *SUPPORT PANEL                                | Dented        | 949.30 FL   | *949.30 FL   |
| 45  | 1   | *SUPPORT PANEL TOP COVER                      | Broken        | 225.30 FL   | *225.30 FL   |
| 46  | 1   | *FRONT BRACE PANEL                            | Broken        | 83.40 FL    | *83.40 FL    |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                   | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------------|---------------|-------------|--------------|
| 47  | 1   |          | *FRONT LH FENDER                              | Dented        | 939.10 FL   | *939.10 FL   |
| 48  | 1   |          | *FRONT LH FENDER SPLASH SHIELD                | Missing       | 198.40 FL   | *187.60 FL   |
| 49  | 1   |          | *FRONT LH FENDER HYBRID EMBLEM                | Necessary     | 52.30 FL    | *52.30 FL    |
| 50  | 1   |          | *FRONT LH FENDER INNER PANEL                  | Broken        | 756.20 FL   | *698.00 FL   |
| 51  | 1   |          | *FRONT LH FENDER INNER UPPER PANEL            | Dented        | 388.40 FL   | *388.40 FL   |
| 52  | 1   |          | *FRONT LH FENDER QUARTER GARNISH              | Dented        | 93.20 FL    | *93.20 FL    |
| 53  | 1   |          | *FRONT RH FENDER                              | Repair        | 939.10 FL   | *- FL        |
| 54  | 1   |          | *FRONT RH FENDER SPLASH SHIELD                | Not Necessary | 198.40 FL   | *- FL        |
| 55  | 1   |          | *FRONT RH FENDER HYBRID EMBLEM                | Necessary     | 52.30 FL    | *52.30 FL    |
| 56  | 1   |          | *BATTERY COVER                                | Broken        | 67.20 FL    | *67.20 FL    |
| 57  | 1   |          | *BATTERY SUPPORT                              | Dented        | 56.80 FL    | *56.80 FL    |
| 58  | 1   |          | *BATTERY FASTENERS BRACKET                    | Dented        | 23.90 FL    | *23.90 FL    |
| 59  | 1   |          | *AIR CLEANER TANK                             | Not Damaged   | 947.40 FL   | *- FL        |
| 60  | 1   |          | *AIR CLEANER TANK AIR FLOW SENSOR             | Not Damaged   | 163.80 FL   | *- FL        |
| 61  | 1   |          | *AIR CLEANER TANK INTAKE HOSE                 | Not Damaged   | 93.00 FL    | *- FL        |
| 62  | 1   |          | *AIR CLEANER TANK INTAKE PIPE                 | Not Damaged   | 54.70 FL    | *- FL        |
| 63  | 1   |          | *AIR CLEANER TANK RESONATOR BOX               | Not Damaged   | 134.60 FL   | *- FL        |
| 64  | 1   |          | *AIR CLEANER TANK INTAKE DUCT                 | Not Damaged   | 149.60 FL   | *- FL        |
| 65  | 1   |          | *AIRCON CONDENSER                             | Bent          | 1,303.60 FL | *1,303.60 FL |
| 66  | 1   |          | *AIRCON CONDENSER FAN MOTOR                   | Jammed        | 543.50 FL   | *478.90 FL   |
| 67  | 1   |          | *AIRCON CONDENSER FAN BLADE                   | Not Damaged   | 233.00 FL   | *- FL        |
| 68  | 1   |          | *AIRCON DISCHARGE PIPE                        | Not Necessary | 333.70 FL   | *- FL        |
| 69  | 1   |          | *AIRCON SUCTION PIPE                          | Not Necessary | 385.50 FL   | *- FL        |
| 70  | 1   |          | *AIRCON LIQUID PIPE                           | Not Necessary | 637.80 FL   | *- FL        |
| 71  | 1   |          | *RADIATOR ASSY                                | Bent          | 1,841.10 FL | *1,841.10 FL |
| 72  | 1   |          | *RADIATOR FAN MOTOR                           | Broken        | 543.50 FL   | *543.50 FL   |
| 73  | 1   |          | *RADIATOR FAN COWLING                         | Broken        | 219.30 FL   | *219.30 FL   |
| 74  | 1   |          | *RADIATOR FAN BLADE                           | Not Damaged   | 181.80 FL   | *- FL        |
| 75  | 1   |          | *RADIATOR TOP HOSE                            | Cut           | 63.70 FL    | *63.70 FL    |
| 76  | 1   |          | *RADIATOR LOWER HOSE                          | Cut           | 40.20 FL    | *40.20 FL    |
| 77  | 1   |          | *RADIATOR SPARE TANK                          | Necessary     | 164.50 FL   | *164.50 FL   |
| 78  | 1   |          | *RADIATOR RH TOP MOUNT                        | Necessary     | 35.80 FL    | *35.80 FL    |
| 79  | 1   |          | *RADIATOR LH TOP MOUNT                        | Necessary     | 35.80 FL    | *35.80 FL    |
| 80  | 1   |          | *RADIATOR RH TOP RUBBER BUSHING               | Necessary     | 19.60 FL    | *19.60 FL    |
| 81  | 1   |          | *RADIATOR LH TOP RUBBER BUSHING               | Necessary     | 19.60 FL    | *19.60 FL    |
| 82  | 1   |          | *RADIATOR RH LOWER RUBBER BUSHING             | Necessary     | 19.60 FL    | *19.60 FL    |
| 83  | 1   |          | *RADIATOR LH LOWER RUBBER BUSHING             | Necessary     | 19.60 FL    | *19.60 FL    |
| 84  | 1   |          | *RADIATOR HYBRID SPARE TANK                   | Broken        | 225.80 FL   | *225.80 FL   |
| 85  | 1   |          | *ENGINE RH MOUNTING                           | Not Damaged   | 382.00 FL   | *- FL        |
| 86  | 1   |          | *GEARBOX MOUNTING                             | Not Necessary | 296.40 FL   | *- FL        |
| 87  | 1   |          | *FRONT LH FUSE BOX TOP COVER                  | Missing       | 178.30 FL   | *178.30 FL   |
| 88  | 1   |          | *FRONT LH FUSE BOX CENTRE                     | Broken        | 394.50 FL   | *394.50 FL   |
| 89  | 1   |          | *FRONT LH FUSE BOX LOWER                      | No such part  | 152.80 FL   | *- FL        |
| 90  | 1   |          | *FRONT HYBRID CONTROL UNIT                    | Broken        | 5,594.10 FL | *4,800.01 FL |
| 91  | 1   |          | *FRONT HYBRID CONTROL UNIT HIGH VOLTAGE CABLE | Not Necessary | 1,783.40 FL | *- FL        |
| 92  | 1   |          | *DRIVER SAFETY BELT                           | Not Necessary | 1,578.90 FL | *- FL        |
| 93  | 1   |          | *PASSENGER SAFETY BELT                        | Not Necessary | 1,578.90 FL | *- FL        |
| 94  | 2   |          | *SRS IMPACT SENSORS                           | Not Necessary | 621.00 FL   | *- FL        |
| 95  | 1   |          | *SRS CONTROL UNIT                             | Not Necessary | 1,137.30 FL | *- FL        |
| 96  | 1   |          | *FRONT LH SIDE MIRROR ASSY                    | Missing       | 971.40 FL   | *971.40 FL   |
| 97  | 1   |          | *FRONT LH SIDE MIRROR COVER                   | Missing       | 71.50 FL    | *71.50 FL    |
| 98  | 1   |          | *FRONT LH DOOR                                | Dented        | 1,218.20 FL | *1,218.20 FL |
| 99  | 1   |          | *FRONT LH DOOR FRAME BLACK TAPE               | Necessary     | 121.10 FL   | *60.00 FL    |
| 100 | 1   |          | *FRONT LH DOOR GLASS                          | Cut           | 643.20 FL   | *643.20 FL   |
| 101 | 1   |          | *FRONT LH DOOR OUTER UPPER MOULDING           | Cut           | 178.30 FL   | *178.30 FL   |
| 102 | 1   |          | *FRONT LH DOOR OUTER HANDLE                   | Dented        | 208.40 FL   | *143.60 FL   |
| 103 | 1   |          | *REAR RH DOOR                                 | Not Damaged   | 1,192.20 FL | *- FL        |
| 104 | 1   |          | *REAR RH DOOR FRAME BLACK TAPE                | Not Damaged   | 121.10 FL   | *- FL        |
| 105 | 1   |          | *REAR RH DOOR OUTER UPPER MOULDING            | Not Damaged   | 178.30 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                | Condition     | Repairer's  | Amount     |
|-----|-----|----------|--------------------------------------------|---------------|-------------|------------|
| 106 | 1   |          | *REAR RH DOOR GLASS                        | Not Damaged   | 603.10 FL   | *- FL      |
| 107 | 1   |          | *REAR RH DOOR OUTER HANDLE                 | Not Damaged   | 208.40 FL   | *- FL      |
| 108 | 1   |          | *REAR RH FENDER                            | Not Damaged   | 936.70 FL   | *- FL      |
| 109 | 1   |          | *REAR RH FENDER GARNISH                    | Not Damaged   | 302.10 FL   | *- FL      |
| 110 | 1   |          | *LH SIDE ROCKER PANEL GARNISH              | Dented        | 977.60 FL   | *645.10 FL |
| 111 | 1   |          | *FRONT LH LOWER ARM                        | Bent          | 498.50 FL   | *435.00 FL |
| 112 | 1   |          | *FRONT LH LOWER ARM BALL JOINT             | Jammed        | 110.10 FL   | *110.10 FL |
| 113 | 1   |          | *FRONT LH KNUCKLE ARM                      | Dented        | 580.80 FL   | *499.30 FL |
| 114 | 1   |          | *FRONT LH SHOCK ABSORBER                   | Bent          | 398.20 FL   | *398.20 FL |
| 115 | 1   |          | *FRONT LH WHEEL BEARING                    | Jammed        | 559.94 FL   | *223.40 FL |
| 116 | 1   |          | *STEERING RACK AND PINION                  | Not Damaged   | 2,301.80 FL | *- FL      |
| 117 | 1   |          | *REAR LH LOWER ARM                         | Not Damaged   | 450.80 FL   | *- FL      |
| 118 | 1   |          | *REAR LH KNUCKLE ARM                       | Not Damaged   | 503.20 FL   | *- FL      |
| 119 | 1   |          | *REAR LH WHEEL BEARING                     | Not Damaged   | 485.30 FL   | *- FL      |
| 120 | 1   |          | *REAR LH SHOCK ABSORBER                    | Not Damaged   | 266.40 FL   | *- FL      |
| 121 | 1   |          | *SET BONNET INSULATOR CLIPS                | Necessary     | 70.00 FS    | *30.00 FS  |
| 122 | 1   |          | *FRONT WINDSCREEN GLASS SEALANT            | Necessary     | 70.00 FS    | *30.00 FS  |
| 123 | 1   |          | *FRONT WINDSCREEN GLASS INNER SEAL         | Necessary     | 50.00 FS    | *30.00 FS  |
| 124 | 1   |          | *FRONT WINDSCREEN GLASS ERP BRACKET        | Necessary     | 26.00 FS    | *26.00 FS  |
| 125 | 1   |          | *SET SUPPORT PANEL TOP COVER CLIPS         | Necessary     | 60.00 FS    | *30.00 FS  |
| 126 | 1   |          | *SET FRONT LH FENDER SPLASH SHIELD CLIPS   | Necessary     | 60.00 FS    | *20.00 FS  |
| 127 | 1   |          | *SET FRONT RH FENDER SPLASH SHIELD CLIPS   | Necessary     | 60.00 FS    | *20.00 FS  |
| 128 | 1   |          | *RADIATOR COOLANT                          | Necessary     | 70.00 FS    | *40.00 FS  |
| 129 | 1   |          | *BATTERY                                   | Broken        | 280.00 FS   | *180.00 FS |
| 130 | 1   |          | *FRONT LH SPORT RIM                        | Cut           | 950.00 FS   | *600.00 FS |
| 131 | 1   |          | *FRONT LH TYRE                             | Not Damaged   | 280.00 FS   | *- FS      |
| 132 | 1   |          | *FRONT LH FENDER INNER PANEL JOINT SEALANT | Necessary     | 80.00 FS    | *30.00 FS  |
| 133 | 1   |          | *REAR LH FENDER JOINT SEALANT              | Necessary     | 70.00 FS    | *30.00 FS  |
| 134 | 1   |          | *REAR LH SPORT RIM                         | Repeated      | 950.00 FS   | *- FS      |
| 135 | 1   |          | *REAR LH TYRE                              | Repeated      | 280.00 FS   | *- FS      |
| 136 | 1   |          | *BRAKE FLUID                               | Not Necessary | 50.00 FS    | *- FS      |
| 137 | 1   |          | *FRONT NUMBER PLATE                        | Bent          | 70.00 FS    | *30.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (S\$) 62,324.84 33,225.51**  
**- List Item Discount on L Items 25.00/25.00% (S\$) 14,712.21 8,032.38**

**Total Parts (S\$) 47,612.63 25,193.13**

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                  |          |                 |                 |
| 1                               | LAOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS | New      | 2,500.00        | 2,000.00        |
| 2                               | SPRAY PAINTING ON AFFECTED PANELS                                                                                                | New      | 1,800.00        | 1,600.00        |
| 3                               | CHECK WIRING AND LIGHTING SYSTEM                                                                                                 | New      | 150.00          | 150.00          |
| 4                               | APPLY RUST COATING CHEMICAL ON AFFECTED PANELS                                                                                   | New      | 150.00          | 60.00           |
| 5                               | REMOVE AND REPLACE AIRCON CONDENSER,PIPES,HOSES AND FAN ASSY.TO REFILL AIRCON GAS                                                | New      | 200.00          | 120.00          |
| 6                               | REMOVE AND REPLACE RADIATOR ASSY,PIPES,HOSES AND FAN ASSY.TO REFILL COOLANT                                                      | New      | 200.00          | 100.00          |
| 7                               | REMOVE AND REPLACE FRONT WINDSCREEN GLASS AND SEALANTS                                                                           | New      | 200.00          | 120.00          |
| 8                               | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR                                                                    | New      | 450.00          | 250.00          |
| 9                               | CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM                                                                                        | New      | 100.00          | 60.00           |
| 10                              | REMOVE AND REPLACE FRONT SAFETY BELTS TO ASSIST REPAIR                                                                           | New      | 350.00          | 0.00            |
| 11                              | REMOVE AND REINSTALL FRONT SAFETY BELTS GARNISH AND TRIMS TO ASSIST REPAIR                                                       | New      | 180.00          | 0.00            |
| 12                              | RESET AND DIAGNOSE AIRBAG AND FAULT CODE AFTER REPAIR                                                                            | New      | 350.00          | 0.00            |
| 13                              | REMOVE AND REINSTALL FRONT LH DOOR INNER PARTS TO NEW DOOR                                                                       | New      | 100.00          | 80.00           |
| 14                              | REMOVE AND REINSTALL REAR LH DOOR INNER PARTS TO NEW DOOR                                                                        | New      | 100.00          | 0.00            |
| 15                              | REMOVE AND REINSTALL REAR LH FENDER INNER TRIMS,GARNISH,SEATS AND ROOF LINING TO ASSIST REPAIR                                   | New      | 350.00          | 0.00            |
| 16                              | REMOVE AND REINSTALL FUEL TANK,PIPES,HOSES AND SENSORS TO ASSIST REPAIR                                                          | New      | 120.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                  |          | <b>7,300.00</b> | <b>4,540.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >