4/19/22, 11:07 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21008596/APA3Q2

19/04/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070156112 **Claimant Vehicle SDK1237Y** Insured Vehicle No: SMW1747Y

No:

Date of Loss: 14/08/2021 Nature of Claim: TP Claim No: 9175897006SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDK1237Y**

Make & Model: CVK078768 AUDI A5, 2.0 (A) Engine No:

Reg. Date: 27/04/2019 (Man. Year: 2019) Chassis No: WAUZZZF54KA036756

Odometer: 29124 km Colour: Grey

Engine Capacity: 1984 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18 Front Left Side: Rear Left Side: Continental 6 mm Continental 6 mm Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,045.00	5,141.76	6,903.24	57.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,932.00	3,952.00	7,980.00	66.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,977.00	9,093.76	14,883.24	62.07
+ GST 7.00/7.00% (S\$)	1,678.39	636.56	1,041.83	62.07
Nett Amount (S\$)	25,655.39	9,730.32	15,925.07	62.07

+ Car Rental (7.0 x S\$150.00/day + 7.00% GST) (S\$) 1,123.50 + Doc/Search Fee (S\$) 2.00

> **Nett Liability (S\$)** 10,855.82

INSPECTION

16/08/2021 Date of Assignment:

Premium Automobiles Pte Ltd (HQ)

Inspected At: 55 UBI ROAD 1 Date Inspected: 20/08/2021 Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: **ADRIAN LING** Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Repair	3,884.00 FS	*-FS
2	1		*FRONT DOOR SEAL -LH	Not Necessary	222.00 FS	*- FS
3	1		*FRONT DOOR BONDING	Not Necessary	49.00 FS	*- FS
4	1		*FRONT DOOR CLEANING SOULTION	Not Necessary	68.00 FS	*- FS
5	1		*FRONT DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*FRONT DOOR CATCH -LH	Not Necessary	120.00 FS	*- FS
7	1		*FRONT DOOR TRIM -LH	Necessary	164.00 FS	*130.80 FS
8	1		*REAR DOOR -LH	Dented	3,884.00 FS	*3,107.20 FS
9	1		*REAR DOOR SEAL -LH	Necessary	222.00 FS	*177.60 FS
10	1		*REAR DOOR BONDING	Not Necessary	49.00 FS	*- FS
11	1		*REAR DOOR CLEANING SOULTION	Not Necessary	68.00 FS	*- FS
12	1		*REAR DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
13	1		*REAR DOOR ATTACHMENT PART	Not Necessary	129.00 FS	*- FS
14	1		*REAR DOOR CATCH	Damaged	120.00 FS	*96.00 FS
15	1		*SIDE MIRROR TRIM -LH	Repair	826.00 FS	*- FS
16	1		*SIDE MEMBER TRIM ATTACHMENT PART	Necessary	130.00 FS	*104.00 FS
17	1		*ADHESIVE TAPES	Necessary	212.00 FS	*169.60 FS
18	1		*REAR ALUMINIUM RIM -LH	Cut	1,690.00 FS	*1,352.00 FS
19	1		*SUNDRIES	Necessary	192.00 FS	*4.56 FS
F=Fra	nchise	part. S=SpcN	lett.	-		
				Total Parts (S\$)	12,045.00	5,141.76
			Report was unsubmitted durir	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGE	New	800.00	280.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR LHS REAR DOOR AND LHS SILL PANEL TRIM RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
3	TO RESPRAY LHS FRONT DOOR DOOR HANDLE ,LHS REAR DOOR AND LHS SILL PANEL TRIM	New	3,500.00	1,650.00
4	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	0.00
5	TO DISMANTLE AND REINSTALL REAR BUMPER .TO REPAIR LHS REAR FENDER RE-ORGANIZ CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,600.00	0.00
6	TO RESPRAY REAR BUMPER AND LHS REAR FENDER	New	2,000.00	550.00
7	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		11,932.00	3,952.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >