

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21008597/R1RS3Q2
Date: 13/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
Claimant Vehicle No :	SHB5217D	Insured Vehicle No :	GBK3417E
Date of Loss:	11/08/2021	Nature of Claim:	TP
		Claim No:	0675656557SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5217D	Engine No:	2ZR2G84474
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU403091674
Reg. Date:	30/11/2020 (Man. Year: 2020)	Odometer:	27818 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,456.60	1,877.12	5,579.48	74.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,332.00	670.00	1,662.00	71.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,788.60	2,547.12	7,241.48	73.98
	+ Loss of Use (6.0 x S\$50.00/day) (S\$)	300.00		
	+ Car Rental (6.0 x S\$90.00/day) (S\$)	540.00		

+ Doc/Search Fee (S\$)	7.00
Nett Liability (S\$)	3,394.12

INSPECTION

Date of Assignment: 12/08/2021

Date Inspected: 12/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Strides Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: MOHD RASUL**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Deformed	485.60 F	*364.20 F
2	1		*PAD ,RR BUMPER ,RH & LH 3 (DISC 25%) (2 PCS)	Necessary	22.00 F	*16.50 F
3	2		*PAD ,RR BUMPER ,RH & LH 2 (DISC 25%)	Necessary	8.00 F	*6.00 F
4	2		*PAD ,RR BUMPER ,RH & LH 1 (DISC 25%)	Necessary	8.00 F	*6.00 F
5	3		*PAD ,RR BUMPER CTR (DISC 25%)	Necessary	33.00 F	*24.75 F
6	1		*SEAL ,RR BUMPER ARM ,RH & LH (DISC 25%) (2 PCS)	Necessary	22.60 F	*16.95 F
7	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	45.00 F	*33.75 F
8	1		*GUARD ,RR BUMPER LOWER (DISC 25%)	Deformed	374.50 F	*280.88 F
9	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX ,RH (DISC 25%)	Scratched	39.00 F	*29.25 F
10	1		*TAILGATE BACK DOOR OUTSIDE GARNISH SUB (DISC 25%)	Cracked	913.60 F	*685.20 F
11	1		*LAMP ASSY ,REAR RH (DISC 10%)	Cracked	293.60 F	*264.24 F
12	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
13	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
14	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
15	1		*PANEL SUB-ASSY ,FENDER REAR RH	Serviceable	871.50 F	*- F
16	2		*PATCH SIDE PANEL REAR END ,RH & LH	Serviceable	33.70 F	*- F
17	1		*LINER ,REAR FENDER ,RH	Serviceable	139.80 F	*- F
18	1		*REAR BUMPER REINFORCEMENT	Serviceable	332.70 F	*- F
19	1		*RETAINER ,RR BUMPER ,RH	Serviceable	132.60 F	*- F
20	1		*RETAINER ,RR BUMPER ,LH	Serviceable	132.60 F	*- F
21	1		*SEAL ,RR BUMPER RH	Serviceable	118.30 F	*- F
22	1		*COVER ,GUARD RR BUMPER LOWER	Serviceable	22.00 F	*- F
23	1		*COVER ,REAR FLOOR UNDER ,RH	Serviceable	175.10 F	*- F
24	1		*COVER ,REAR FLOOR UNDER CENTER	Serviceable	229.90 F	*- F
25	1		*LENS & BODY REAR COMBINATION LAMP RH	Serviceable	339.60 F	*- F
26	1		*COVER ,REAR COMBINATION LAMP RH	Serviceable	69.90 F	*- F
27	1		*LENS & BODY REAR COMBINATION LAMP ,NO.2	Serviceable	261.00 F	*- F
28	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
29	1		*ANTENNA ELETRICAL KEY	Serviceable	72.00 F	*- F
30	1		*END PANEL SUB-ASSY ,BODY LOWER BACK	Serviceable	651.00 F	*- F
31	1		*COVER ,REAR FLOOR UNDER CENTER	Serviceable	229.90 F	*- F
32	1		*EMBLEM SUB-ASSY REAR	Not Necessary	47.90 F	*- F
33	1		*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT	Not Necessary	54.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
34	1		*NAME PLATE (PRIUS) LUGGAGE COMPARTMENT	Not Necessary	54.60 F	*- F	
35	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	Repair	913.60 F	*- F	
					Total Parts (\$)	7,456.60	1,877.12

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	300.00
2	SPRAY PAINT	New	1,296.00	300.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	40.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
6	TO WASH AND VACUUM	New	60.00	0.00
			Gross Labour Cost (S\$)	2,332.00
				670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >