

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21008604/KTF3E2

Date: 04/10/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29135698AT2

Claimant Vehicle No : SLM5962E

Insured Vehicle No : SGP7494U

Date of Loss: 12/08/2021

Nature of Claim: TP

Claim No: 637520

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM5962E**

Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) Engine No: 4A92CN6271

Reg. Date: 04/04/2017 (Man. Year: 2016)

Chassis No: JMYSRCY1AGU006473

Colour: Metallic Grey

Odometer: 52542 km

Engine Capacity: 1590 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Nexen 9 mm

Rear Left Side: Nexen 9 mm

Front Right Side: Nexen 9 mm

Rear Right Side: Nexen 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,554.10	2,794.50	759.60	21.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	910.00	290.00	24.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,754.10	3,704.50	1,049.60	22.08
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	4,754.10	2,900.00	1,854.10	39.00
+ GST 7.00/7.00% (S\$)	332.79	203.00	129.79	39.00
Nett Amount (S\$)	5,086.89	3,103.00	1,983.89	39.00

INSPECTION

Date of Assignment: 17/08/2021

Date Inspected: 23/08/2021

Inspected At:

Bifrost Auto Pte Ltd (HQ)
176 Sin Ming Drive, #03-09
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2021)

Parts: 143 MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM5962E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	858.00 FL	*858.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	390.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER	Serviceable	20.00 FL	*- FL
5	1		*O/S FRONT BUMPER FOG LAMP COVER	Missing	32.00 FL	*32.00 FL
6	1		*O/S FRONT BUMPER FOG LAMP	Serviceable	414.00 FL	*- FL
7	1		*O/S HEADLAMP	Mtg Cracked	698.00 FL	*698.00 FL
8	1		*O/S HEADLAMP BRACKET	Repair	20.00 FL	*- FL
9	1		*O/S FRONT FENDER	Bent	588.00 FL	*588.00 FL
10	1		*O/S FRONT FENDER UNDER SHIELD	Cracked	102.00 FL	*102.00 FL
11	8		*O/S FRONT FENDER UNDER SHIELD CLIPS	Necessary	24.00 FL	*24.00 FL
12	1		*WASHER TANK	Dented	81.00 FL	*81.00 FL
13	1		*FRONT RH RIM	Dented	692.00 FL	*692.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,949.00	3,105.00
- List Item Discount on L Items 10.00/10.00% (S\$)	394.90	310.50
Total Parts (S\$)	3,554.10	2,794.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINTING	New	600.00	400.00
2	TO CHECK FRONT WIRING & FOCUS HEADLIGHT	New	30.00	20.00
3	TO ANTI RUST	New	30.00	30.00
4	LABOUR	New	480.00	400.00
5	CHECK WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (\$)			1,200.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >