

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21008606/T1QCN2**Date:** 27/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00053952100

**Claimant Vehicle No :** SMM9776M **Insured Vehicle No :** GBC4492Y

Date of Loss: 14/08/2021 Nature of Claim: TP Claim No: SNM21D204519/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMM9776M**

Make & Model: TOYOTA C-HR HYBRID, 1.8 E G CVT (A) Engine No: 2ZR8180418

Reg. Date: 22/07/2019 (Man. Year: 2017) Chassis No: ZYX102069782

Colour: Black Odometer: 43160 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,237.50	2,790.22	1,447.28	34.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,630.00	2,120.00	56.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,987.50</b>	<b>4,420.22</b>	<b>3,567.28</b>	<b>44.66</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	559.13	309.42	249.71	44.66
<b>Nett Amount (\$\$)</b>	<b>8,546.63</b>	<b>4,729.64</b>	<b>3,816.99</b>	<b>44.66</b>

**INSPECTION**

Date of Assignment: 17/08/2021

Date Inspected: 18/08/2021 Inspected At: BLK 3007 UBI ROAD 1 #01-450  
SINGAPORE 408700  
REPAIRER: JACK CARS ENTERPRISE PTE LTD

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2021)
<b>Parts:</b>	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM9776M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	900.00 FL	*685.10 FL
2	1		*REAR BUMPER DIFFUSER	Deformed	400.00 FL	*400.00 FL
3	1		*REAR BOOT	Bent	1,200.00 FL	*1,112.50 FL
4	1		*REAR BOOT GARNISH	Cracked	210.00 FL	*210.00 FL
5	1		*REAR END PANEL	Repair	780.00 FL	*- FL
6	1		*REAR END PANEL TOP COVER	Deformed	180.00 FL	*180.00 FL
7	1		*BOOT LOCK-UPPER	Bent	320.00 FL	*320.00 FL
8	1		*BOOT LOCK COVER-UPPER	Cut	100.00 FL	*100.00 FL
9	1		*REAR SUPPORT BEAM	Bent	600.00 FL	*322.30 FL
10	1		*BUMPER CLIPS	Necessary	150.00 FS	*30.00 FS
11	1		*TOYOTA EMBLEM	Necessary	150.00 FS	*72.20 FS
12	1		*CHR EMBLEM	Necessary	95.00 FS	*55.60 FS
13	1		*HYBRID EMBLEM	Necessary	75.00 FS	*75.00 FS
14	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
15	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,410.00</b>	<b>3,622.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,172.50	832.48
<b>Total Parts (\$\$)</b>	<b>4,237.50</b>	<b>2,790.22</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,000.00	700.00
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS;KNOCK,JACK,WELD,RESHAPE AND ALIGN ALL AFFECTED PORTIONS	New	1,500.00	600.00
3	TO CHECK LIGHTING SYSTEM,WIRING & REWIRE	New	250.00	30.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	220.00	60.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	280.00	60.00
6	TO REMOVE & REINSTALL SENSORS	New	100.00	30.00
7	TO REMOVE & REINSTALL REAR WINDSCREEN	New	200.00	120.00
8	ANTI RUST TREATMENT	New	200.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,750.00</b>	<b>1,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >