

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21008607/ETCE2

Date: 27/09/2021

REFERENCE

Insured/Claimant:	FAHEEM AHMED KHAN	Policy No:	2070103559		
Date of Loss:	14/08/2021	Nature of Claim:	OD	Claim No:	0208457248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT6463Z		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11CC5721
Reg. Date:	09/07/2020 (Man. Year: 2019)	Chassis No:	GF7W0700365
Colour:	Blue	Odometer:	7329 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,799.52	4,519.63	5,279.89	53.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,120.00	5,020.00	5,100.00	50.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,919.52	9,539.63	10,379.89	52.11
+ GST 7.00/7.00% (S\$)	1,394.37	667.77	726.60	52.11
Nett Amount (S\$)	21,313.89	10,207.40	11,106.49	52.11

INSPECTION

Date of Assignment: 17/08/2021

Date Inspected: 17/08/2021 Inspected At:

Estimated Period of Repair: 15.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Cut	220.00 FS	*220.00 FS
2	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Broken	1,048.00 FL	*1,048.00 FL
4	1		*EXTENSION, FR BUMPER	Cut	517.00 FL	*517.00 FL
5	1		*COVER, FR BUMPER	Cut	361.00 FL	*361.00 FL
6	1		*GARNISH, FR BUMPER SIDE (RH)	Broken	48.00 FL	*48.00 FL
7	1		*GARNISH, FR BUMPER SIDE (LH)	Cracked	48.00 FL	*48.00 FL
8	1		*GARNISH, FR BUMPER SIDE (RH)	Broken	220.00 FL	*220.00 FL
9	1		*GARNISH, FR BUMPER SIDE (LH)	Broken	220.00 FL	*220.00 FL
10	1		*GARNISH, FR BUMPER SIDE (RH)	Broken	112.00 FL	*112.00 FL
11	1		*GARNISH, FR BUMPER SIDE (LH)	Broken	112.00 FL	*112.00 FL
12	1		*REINFORCEMENT, FR BUMPER	Not Necessary	510.00 FL	*- FL
13	1		*REINFORCEMENT, FR BUMPER	Not Necessary	135.00 FL	*- FL
14	1		*GRILLE ASSY, RADIATOR	Not Necessary	550.00 FL	*- FL
15	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	50.00 FL	*- FL
16	1		*FACE, RR BUMPER	Broken	811.00 FL	*811.00 FL
17	1		*BRKT, R/BMPR FACE SIDE, LH	Not Necessary	12.00 FL	*- FL
18	1		*BRKT, R/BMPR FACE SIDE, RH	Not Necessary	12.00 FL	*- FL
19	1		*REINFORCEMENT, RR BUMPER, LH	Not Necessary	79.00 FL	*- FL
20	1		*REINFORCEMENT, RR BUMPER, RH	Not Necessary	79.00 FL	*- FL
21	10		*CLIP, FR BUMPER	Necessary	40.00 FL	*40.00 FL
22	1		*EXTENSION, RR BUMPER	Broken	360.00 FL	*289.00 FL
23	1		*MOULDING, RR BUMPER, LH	Necessary	88.00 FL	*88.00 FL
24	1		*MOULDING, RR BUMPER, RH	Necessary	88.00 FL	*88.00 FL
25	1		*MOULDING, RR WHEEL ARCH, LH	Not Necessary	168.00 FL	*- FL
26	1		*MOULDING, RR WHEEL ARCH, RH	Not Necessary	168.00 FL	*- FL
27	1		*REFLECTOR, TAIL LAMP, LH	Not Necessary	100.00 FL	*- FL
28	1		*REFLECTOR, TAIL LAMP, RH	Not Necessary	100.00 FL	*- FL
29	1		*LAMP ASSY, COMB, RR LH	Not Necessary	603.00 FL	*- FL
30	1		*LAMP ASSY, COMB, RR RH	Not Necessary	603.00 FL	*- FL
31	1		*LAMP ASSY, TAIL, LH	Not Necessary	506.00 FL	*- FL
32	1		*LAMP ASSY, TAIL, RH	Not Necessary	506.00 FL	*- FL
33	1		*MARK, OUTLANDER	Necessary	95.00 FL	*95.00 FL
34	1		*PANEL, RR END	Dented	326.00 FL	*326.00 FL
35	1		*PANEL, RR END, INR LH (NPA)	Not Necessary	0.00 FL	*- FL
36	1		*PANEL, RR END, INR RH	Not Necessary	146.00 FL	*- FL
37	1		*FLOOR, RR	Repair	751.00 FL	*- FL
38	1		*TRIM, RR END	Crushed	113.00 FL	*113.00 FL
39	1		*BOX, CARGO FLOOR	Broken	204.00 FL	*204.00 FL
40	1		*LID, CARGO FLOOR BOX	Not Necessary	295.00 FL	*- FL
41	1		*W/STRIP, TAILGATE OPENING	Torn	213.00 FL	*213.00 FL
42	1		*STRIKER, TAILGATE LATCH	Not Necessary	20.00 FL	*- FL
43	1		*LATCH, TAILGATE	Not Necessary	385.00 FL	*- FL
44	1		*MOULDING, FR BUMPER, LH	Necessary	97.00 FL	*97.00 FL
45	1		*MOULDING, FR BUMPER, RH	Necessary	97.00 FL	*97.00 FL
46	1		*MOULDING, FR WHEEL ARCH, LH	Not Necessary	168.00 FL	*- FL
47	1		*MOULDING, FR WHEEL ARCH, RH	Not Necessary	168.00 FL	*- FL
48	1		*TRIM, RR SHELF	Not Necessary	672.00 FL	*- FL
49	1		*BUZZER, KEYLESS OPERATIO, RR (Supplementary)	Broken	91.00 FL	*91.00 FL
50	1		*MARK, THREE-DIAMOND (Supplementary)	Necessary	61.00 FL	*61.00 FL
51	2		*SILENCER, FLOOR (Supplementary)	Necessary	28.00 FL	*28.00 FL
52	1		*EMBLEM MIVEC TECHNOLOGY (Supplementary)	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*REAR BUMPER PLATE (CHROME) (Supplementary)	Bent	192.00 FL	*192.00 FL
			F=Franchise part. S=SpcNett. L=ListItemDisc.			
					Sub Total (\$)	12,646.00
					- List Item Discount on L Items 23.00/23.00% (\$)	2,846.48
					Total Parts (\$)	9,799.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW (FR PORTION) FR BUMPER. REPAIR LHF FENDER	New	1,350.00	450.00
2	RENEW (RR PORTION) RR BUMPER, RR END PNL & RR FLR PNL. REPAIR TAILGATE, LHR FENDER, RHR FENDER & RR CHASSIS	New	3,150.00	1,800.00
3	RESPRAY RR BUMPER, RR END PNL, TAILGATE, RR FLR PANEL, LHR FENDER, RHR FENDER, RR CHASSIS, FR BUMPER & LHF FENDER	New	3,150.00	1,750.00
4	REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT TO FACILITATE REPAIR	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	CONDUCT CHASSIS ALIGNMENT-CELETTE BENCH	New	1,000.00	500.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
9	SUPPLY FR NUMBER PLATE WITH CASING	New	50.00	50.00
10	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00
11	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
12	SUPPLY FR CAMERA (FR GRILLE)	New	780.00	0.00
13	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
14	SUPPLY BODY PNL SEALANT	New	60.00	60.00
15	SUPPLY C&C BADGE	New	40.00	40.00
Gross Labour Cost (\$\$)			10,120.00	5,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >