

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008608/UQCN2**Date:** 06/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00021662101	
Claimant Vehicle No :	SKV4526C	Insured Vehicle No :	YM8097D	
Date of Loss:	12/08/2021	Nature of Claim:	TP	Claim No: SNM21D204480/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV4526C	Engine No:	L15B4021902
Make & Model:	HONDA VEZEL, 1.5 S (A)	Chassis No:	RU11101901
Reg. Date:	18/09/2015 (Man. Year: 2015)	Odometer:	92618 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,226.80	0.00	4,226.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	500.00	1,030.00	67.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	5,756.80	500.00	5,256.80	91.31

INSPECTION

Date of Assignment:	17/08/2021		
Date Inspected:	17/08/2021	Inspected At:	Blk 15 Kaki Bukit Road 4, Bartley Biz Centre Repairer: Zoom Autowerks Pte Ltd
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2022)
Parts:	143	HONDA VEZEL 1.5 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV4526C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,085.40 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	60.30 FL	*- FL
3	1		*FRONT FENDER	Not Necessary	580.40 FL	*- FL
4	1		*FRONT FENDER WHEEL HOUSE	Not Necessary	675.00 FL	*- FL
5	1		*FRONT FENDER WHEEL ARCH GARNISH	Not Necessary	488.30 FL	*- FL
6	1		*FRONT RIM LH	Repair	1,350.40 FL	*- FL
7	1		*FRONT SIDE MIRROR ASSEMBLY LH	Repair	606.20 FL	*- FL
8	1		*FRONT TIRE LH	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,196.00	0.00
- List Item Discount on L Items 20.00/20.00% (S\$)	969.20	0.00
Total Parts (S\$)	4,226.80	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	0.00
2	TO APPLY UNDERCOATING	New	150.00	0.00
3	LABOUR FOR REPLACED PARTS AND ALIGNMENT	New	600.00	300.00
4	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	600.00	200.00
Gross Labour Cost (\$\$)			1,530.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >