

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC21008609/R1vce2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	23/08/2021	
			Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YP 4670J	Veh. Inspected	SGT 3380U	
	Policy No.	Z20VC05006312	Coverage (\$)	0.00	
	Claim No.	20/21/21/VC05/024851	Excess (\$)	0.00	
	Assign From	GERALD POH WEE BIN	Assign Date	17/08/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CITY CVT	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	MRHGD86907P030111	Colour	BLACK	
	Odometer	300374 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/50 R15	WINDFORCE	6 mm	
	L/H Front Tyre	195/50 R15	WINDFORCE	6 mm	
	R/H Rear Tyre	195/50 R15	WINDFORCE	6 mm	
	L/H Rear Tyre	195/50 R15	WINDFORCE	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S FRONT PORTION.			
5.	General Information				
	Accident Date	14/08/2021	Inspect Date / Time	17/08/2021 (01:58 PM)	
	Survey held at	U E MOTOR			
		BLK 3006, UBI ROAD 1 #01-334 SINGAPORE 408700			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21008609/R1vce2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser