

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21008611/T1TF3E2**Date:** 21/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070133438
Claimant Vehicle No :	SMP9123G	Insured Vehicle No :	SLS2008Z
Date of Loss:	15/08/2021	Nature of Claim:	TP
		Claim No:	8095766120SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP9123G	Engine No:	HR12046560K
Make & Model:	NISSAN NOTE, 1.2 CVT (A)	Chassis No:	JN1TAAE12Z0983302
Reg. Date:	22/10/2019 (Man. Year: 2019)	Odometer:	11325 km
Colour:	Red		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/08/2021	Garage 13 Pte Ltd (HQ)
Date Inspected:	17/08/2021 Inspected At:	8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
Estimated Period of Repair:	10.0 days	Singapore 415875

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$64,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE OPC	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Deformed	0.00 F	*- F
3	1		*FRT BUMPER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
7	1		*FRT BUMPER TOP GARNISH	Deformed	0.00 F	*- F
8	1		*FRT GRILLE	Cut	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	1		*FRT GRILLE CHROME MOULDING	Cut	0.00 F	*- F
11	1		*FRT SUPPORT PANEL	* Check	0.00 F	*- F
12	1		*FRT LH HEADLAMP ASSY	* Check	0.00 F	*- F
13	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
14	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
15	1		*RADIATOR	* Check	0.00 F	*- F
16	1		*REAR NUMBER PLATE OPC	Necessary	0.00 F	*- F
17	1		*REAR BUMPER	Deformed	0.00 F	*- F
18	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
19	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
20	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
21	1		*REAR END PANEL	* Check	0.00 F	*- F
22	1		*REAR END PANEL TOP GARNISH	* Check	0.00 F	*- F
23	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
24	1		*TAILGATE	Bent	0.00 F	*- F
25	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
26	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
27	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
28	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
29	1		*TAILGATE RUBBER	Necessary	0.00 F	*- F
30	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
31	1		*REAR LH FENDER	Repair	0.00 F	*- F
32	1		*SPARE TYRE BOARD	* Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >