

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21008613/KPS3Q2
Date: 18/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900258675	
Claimant Vehicle No :	SMU4306C	Insured Vehicle No :	GBK784P	
Date of Loss:	15/08/2021	Nature of Claim:	TP	Claim No: 9203928364SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU4306C		
Make & Model:	HONDA FREED HYBRID, 1.5 (A)	Engine No:	LEB7218313
Reg. Date:	13/08/2020 (Man. Year: 2020)	Chassis No:	GB73115727
Colour:	Metallic Blue	Odometer:	118305 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	INTERTRAC 8 mm	Rear Left Side:	Sunride 3 mm
Front Right Side:	INTERTRAC 8 mm	Rear Right Side:	Sunride 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,237.92	6,667.04	1,570.88	19.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,810.00	890.00	32.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,937.92	8,477.04	2,460.88	22.50
Approved Total (Overridden) (S\$)		6,750.00		

(S\$)	10,937.92	6,750.00	4,187.92	38.29
+ GST 7.00/7.00% (S\$)	765.65	472.50	293.15	38.29
Nett Amount (S\$)	11,703.57	7,222.50	4,481.07	38.29
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		7,834.50		

INSPECTION

Date of Assignment: 17/08/2021

Date Inspected: 17/08/2021

Estimated Period of Repair: 6.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,295.00 FL	*1,207.90 FL
2	1		*TAILGATE FREED EMBLEM	Necessary	76.50 FL	*76.50 FL
3	1		*TAILGATE HYBRID EMBLEM	Necessary	88.20 FL	*88.20 FL
4	1		*TAILGATE CHROME MOULDING	Mtg Cracked	118.50 FL	*118.50 FL
5	1		*REAR WINDSCREEN	Shattered	1,140.20 FL	*1,140.20 FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	115.00 FL	*115.00 FL
7	1		*TAILGATE RUBBER	Distorted / Cut	136.70 FL	*136.70 FL
8	1		*TAILGATE INNER LOCK	Dented	156.20 FL	*156.20 FL
9	1		*TAILGATE INNER TRIM BOARD	Mtg Cracked	220.30 FL	*220.30 FL
10	1		*TAILGATE LAMP LH	Mtg Cracked	396.20 FL	*380.20 FL
11	1		*TAILGATE LAMP RH	Cracked	396.20 FL	*380.20 FL
12	1		*REAR FENDER LAMP LH	Cut	590.90 FL	*590.90 FL
13	1		*REAR FENDER LAMP RH	Cracked	590.90 FL	*590.90 FL
14	1		*REAR BUMPER	Bent	873.10 FL	*873.10 FL
15	1		*REAR BUMPER TOW COVER	Serviceable	32.00 FL	*- FL
16	1		*REAR BUMPER SIDE BRACKET LH	Repair	58.00 FL	*- FL
17	1		*REAR BUMPER SIDE BRACKET RH	Repair	58.00 FL	*- FL
18	1		*REAR END PANEL UPPER COVERING	Buckled	112.00 FL	*112.00 FL
19	1		*REAR END PANEL	Bent	560.00 FL	*560.00 FL
20	1		*REAR FLOOR PANEL	Repair	984.50 FL	*- FL
21	2		*REAR REVERSE SENSOR	Cracked	884.00 FL	*572.00 FL
22	2		*REAR REVERSE SENSOR HOLDER	Cracked	190.00 FL	*190.00 FL
23	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
24	1		*REAR TAILGATE INNER TRIM CLIPS	Necessary	40.00 FS	*40.00 FS
25	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
26	1		*REAR BUMPER REVERSE SENSOR	Cracked	250.00 FS	*200.00 FS
27	1		*REAR END PANEL UPPER COVERING CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*REAR CAMERA	Missing	550.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,052.40	8,168.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,814.48	1,501.76
Total Parts (\$\$)	8,237.92	6,667.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE,REFIX & REPAIR REAR ACCIDENT AREA	New	1,000.00	700.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA	New	1,000.00	800.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
6	TO CONDUCT DIAGNOSTIC ,RESET FAULT CODE & MEMORY	New	150.00	0.00
7	TO CHECK WIRING & CENTRAL LOCKING SYSTEM	New	80.00	20.00
8	TO TUFF COAT AND UNDERSEAL MATERIAL	New	100.00	60.00
Gross Labour Cost (\$\$)			2,700.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >