

Date: 16.08.2021

Vehicle No: SMU4306C

Model: HONDA FREED HYBRID 1.5G

Chassis: GB73115727

Reg.Year: 2020

Third Party Insurer: AIG

Third Party Veh No: GBK784P

Date of Accident: 15.08.2021

Estimator: Victor

Surveyor:

Not Authorized
Penalty B4 pain
6 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	TAILGATE	1		\$1,295.00
2	TAILGATE "FREED" EMBLEM	1		\$76.50
3	TAILGATE "HYBRID" EMBLEM	1		\$88.20
4	TAILGATE CHROME MOULDING	1		\$118.50
5	REAR WINDSCREEN	1		\$1,140.20
6	REAR WINDSCREEN MOULDING	1		\$115.00
7	TAILGATE RUBBER	1		\$136.70
8	TAILGATE INNER LOCK	1		\$156.20
9	TAILGATE INNER TRIM BOARD	1		\$220.30
10	TAILGATE LAMP LH	1		\$396.20
11	TAILGATE LAMP RH	1		\$396.20
12	REAR FENDER LAMP LH	1		\$590.90
13	REAR FENDER LAMP RH	1		\$590.90
14	REAR BUMPER	1		\$873.10
15	REAR BUMPER TOW COVER	1		\$32.00
16	REAR BUMPER SIDE BRACKET LH	1		\$58.00
17	REAR BUMPER SIDE BRACKET RH	1		\$58.00
18	REAR END PANEL UPPER COVERING	1		\$112.00
19	REAR END PANEL	1		\$560.00
20	REAR FLOOR PANEL	1		\$984.50

SUB TOTAL	\$7,998.40
LESS 20%	-\$1,599.68
PARTS TOTAL	\$6,398.72

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		\$60.00
2	REAR TAILGATE INNER TRIM CLIPS	1		\$40.00
3	REAR BUMPER CLIPS	1		\$50.00
4	REAR BUMPER REVERSE SENSOR	1		\$250.00
5	REAR END PANEL UPPER COVERING CLIPS	1		\$30.00
6	REAR CAMERA	1		\$550.00
S/N TOTAL				\$980.00

Head office

5 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 0910 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 16.08.2021
Vehicle No: SMU4306C
Model: HONDA FREED HYBRID 1.5G
Chassis: GB73115727
Reg.Year: 2020

Third Party Insurer: AIG
Third Party Veh No: GBK784P
Date of Accident: 15.08.2021
Estimator: Victor
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR REAR ACCIDENT AREA.	\$1,000.00	700
LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA.	\$1,000.00	800
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$150.00	120
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM.	\$120.00	60
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	50
TO CONDUCT DIAGNOSTIC, RESET FAULT CODE & MEMORY.	\$150.00	?
TO CHECK WIRING & CENTRAL LOCKING SYSTEM.	\$80.00	20
TO TUFF COAT AND UNDERSEAL MATERIAL.	\$100.00	60
LABOUR TOTAL		\$2,700.00

Vic	TOTAL	\$10,078.72
-----	--------------	--------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 150143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

