

# OPTIMA WERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD  
Co. Reg. No. 201212455W

www.ow.sg

/OptimaWerkz

/OptimaWerkz

Date: 16.08.2021

Vehicle No: SMU4306C

Model: HONDA FREED HYBRID 1.5G

Chassis: GB73115727

Reg. Year: 2020

Third Party Insurer: AIG

Third Party Veh No: GBK784P

Date of Accident: 15.08.2021

Estimator: Victor

Surveyor:

*Not Authorized  
Permanently B4 pain  
6 days  
1/1 Rng @ 6750h*

## ESTIMATE

| NO. | DESCRIPTION                    | QTY | UNIT S\$     | AMOUNT S\$ |
|-----|--------------------------------|-----|--------------|------------|
| 1   | TAILGATE <i>1207.90</i>        | 1   | <i>My</i>    | \$1,295.00 |
| 2   | TAILGATE "FREED" EMBLEM        | 1   | <i>My</i>    | \$76.50    |
| 3   | TAILGATE "HYBRID" EMBLEM       | 1   | <i>My</i>    | \$88.20    |
| 4   | TAILGATE CHROME MOULDING       | 1   | <i>My</i>    | \$118.50   |
| 5   | REAR WINDSCREEN                | 1   | <i>Photo</i> | \$1,140.20 |
| 6   | REAR WINDSCREEN MOULDING       | 1   | <i>My</i>    | \$115.00   |
| 7   | TAILGATE RUBBER                | 1   | <i>My/My</i> | \$136.70   |
| 8   | TAILGATE INNER LOCK            | 1   | <i>My</i>    | \$156.20   |
| 9   | TAILGATE INNER TRIM BOARD      | 1   | <i>My</i>    | \$220.30   |
| 10  | TAILGATE LAMP LH <i>380.20</i> | 1   | <i>My</i>    | \$396.20   |
| 11  | TAILGATE LAMP RH <i>380.20</i> | 1   | <i>CM</i>    | \$396.20   |
| 12  | REAR FENDER LAMP LH            | 1   | <i>CM</i>    | \$590.90   |
| 13  | REAR FENDER LAMP RH            | 1   | <i>CM</i>    | \$590.90   |
| 14  | REAR BUMPER                    | 1   | <i>My</i>    | \$873.10   |
| 15  | REAR BUMPER TOW COVER          | 1   | <i>My</i>    | \$32.00    |
| 16  | REAR BUMPER SIDE BRACKET LH    | 1   | <i>My</i>    | \$58.00    |
| 17  | REAR BUMPER SIDE BRACKET RH    | 1   | <i>My</i>    | \$58.00    |
| 18  | REAR END PANEL UPPER COVERING  | 1   | <i>My</i>    | \$112.00   |
| 19  | REAR END PANEL                 | 1   | <i>My</i>    | \$560.00   |
| 20  | REAR FLOOR PANEL               | 1   | <i>My</i>    | \$984.50   |

*Rear reverse sensor x2 @ 442 x2 CM ✓ @ 286*  
*holder x2 @ 95 x2 CM ✓*

|             |             |
|-------------|-------------|
| SUB TOTAL   | \$7,998.40  |
| LESS 20%    | -\$1,599.68 |
| PARTS TOTAL | \$6,398.72  |

| NO.       | SPECIAL NETT                        | QTY | UNIT S\$  | AMOUNT S\$ |
|-----------|-------------------------------------|-----|-----------|------------|
| 1         | REAR WINDSCREEN SEALANT             | 1   | <i>My</i> | \$60.00    |
| 2         | REAR TAILGATE INNER TRIM CLIPS      | 1   | <i>My</i> | \$40.00    |
| 3         | REAR BUMPER CLIPS                   | 1   | <i>My</i> | \$50.00    |
| 4         | REAR BUMPER REVERSE SENSOR          | 1   | <i>CM</i> | \$250.00   |
| 5         | REAR END PANEL UPPER COVERING CLIPS | 1   | <i>My</i> | \$30.00    |
| 6         | REAR CAMERA                         | 1   | <i>My</i> | \$550.00   |
| S/N TOTAL |                                     |     |           | \$980.00   |

### Head office

8 Kung Chong Road Singapore 159149  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

8A Serangoon North Ave 5 Singapore 554800  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568042  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 16.08.2021  
Vehicle No: SMU4306C  
Model: HONDA FREED HYBRID 1.5G  
Chassis: GB73115727  
Reg.Year: 2020

Third Party Insurer: AIG  
Third Party Veh No: GBK784P  
Date of Accident: 15.08.2021  
Estimator: Victor  
Surveyor:

**LABOUR CHARGES:**

|                                                                              |            |     |
|------------------------------------------------------------------------------|------------|-----|
| LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR REAR ACCIDENT AREA.        | \$1,000.00 | 700 |
| LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA. | \$1,000.00 | 800 |
| LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.                      | \$150.00   | 120 |
| LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM.        | \$120.00   | 60  |
| LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.         | \$100.00   | 50  |
| TO CONDUCT DIAGNOSTIC, RESET FAULT CODE & MEMORY.                            | \$150.00   | 7   |
| TO CHECK WIRING & CENTRAL LOCKING SYSTEM.                                    | \$80.00    | 20  |
| TO TUFF COAT AND UNDERSEAL MATERIAL.                                         | \$100.00   | 60  |
| LABOUR TOTAL                                                                 | \$2,700.00 |     |

Vic

**TOTAL****\$10,078.72**

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

**Branch (Motor Insurance Claims)**

81K 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

