



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 976H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	3,300.00	-
1	FRONT FENDER LHS	TO REPAIR SEE LABOUR	1,300.00	-
1	FRONT FENDER INNER SHIELD LHS	SERVICEABLE	240.00	-
1	FRONT WHEEL ARCH MOULDING LHS	TO REPAIR SEE LABOUR	240.00	-
1	FRONT HEADLAMP LHS	SERVICEABLE	3,200.00	-
	LESS 20% DISCOUNT		-1,656.00	-
			6,624.00	-
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	60.00	-
			60.00	-
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT FENDER LHS AND FRONT WHEEL ARCH MOULDING LHS.		1,200.00	150.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,000.00	500.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.	NOT NECESSARY	100.00	-
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
			2,400.00	650.00
	GRAND TOTAL		9,084.00	650.00
	RECOMMENDED COST OF REPAIRS			650.00

Report Ref No. CS/SMR21008617/Kuf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.