



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS3/ASM21008619/Gvce2 Date: 24/08/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHC 7106Y	Veh. Inspected	SMA 5139S	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S1M03FRN	Excess (\$)	0.00	
Assign From	CHAN KIAN CHUAN	Assign Date	17/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71205818	Colour	BLUE	
Odometer	230269 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	HABILEAD	6 mm	
L/H Front Tyre	185/60 R15	HABILEAD	6 mm	
R/H Rear Tyre	185/60 R15	HABILEAD	6 mm	
L/H Rear Tyre	185/60 R15	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	14/08/2021	Inspection Date	18/08/2021	
Survey held at	KENT AUTO SERVICES 2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	