

GREEN STAR SPRAY PAINTING

f : facebook.com/greenstarspraypainting

Date: 19.05.2021

CUSTOMER SIGNATURE

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Our Ref: WG/TP/2021-78
Invoice No: TP/GS/2021-78 Date 10 May 2021
Vehicle No: SLM8039B
Attn: MOHAMAD RIZAL BIN ABDUL RAHIM
Company: GREEN STAR SPRAY PAINTING GARAGE
Address: Blk 3011, Bedok North Ave 4, #01-2004/2006 . Bedok Industrial Park E. Singapore 489977

Invoice

Surveyor Fee: S\$260
Re-inspection Fee: Na
Transport: S\$60
Photographs: S\$14/- (@ \$1 per photo, total 14 photos)
Total: S\$334

Surveyor: Winsong Goh
Signature:
Date: 10 May 2021



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : MOHAMAD RIZAL BIN ABDUL RAHIM
C/O GREEN STAR SPRAY PAINTING GARAGE
Blk 3011, Bedok North Ave 4, #01-2004/2006
Bedok Industrial Park E, Singapore 489977

Date : 10 May 2021
Our Ref : WG/TP/2021-78

REFERENCE PARTICULARS

Date of Accident : 30 March 2021
Date of Inspection : 06 April 2021

Type of Inspection : Third Party Claim
Date of Re-Inspn : Na

VEHICLE PARTICULARS

Registration No : SLM8039B
Make : MITSUBISHI
Model : LANCER EX 1.6 AT LED TAIL LAMP
Year : 2016

Engine No : 4A92CN5511
Chassis No : JMYSRCY1AGU006432
Odometer : 21369km
Colour : Blue

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>
Front Near side	: Yokohama	215/55R16
Front Off Side	: Yokohama	215/55R16
Rear Near Side	: Yokohama	215/55R16
Rear off Side	: Yokohama	215/55R16

<u>Thread Balance</u>
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portions.
details, refer to assessment for repairs and photograp attached.

For

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$2,150.00** nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Three (03) working days.

Enclosed Fourteen (14) photographs depicting damage to the vehicle.

Inspection conducted at : GREEN STAR SPRAY PAINTING GARAGE
Blk 3011, Bedok North Ave 4, #01-2004/2006 . Bedok Industrial Park E, Singapore 489977

In accordance to your instruction, we have **not authorise** repairs and inspection
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : SLM8039B
MODEL : LANCER EX 1.6 AT LED TAIL LAMP

Our Ref : WG/TP/2021-78

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

		QTY	ASSESSED		ORIGINAL	REVISED
A)	SPARE PARTS	PC/SET	CONDITION		QUOTATION	QUOTATION
01	REAR BUMPER	1	CRACKED		\$ 841.00	\$ 841.00
02	REAR BUMPER SIDE BRACKET LH	1	NECESSARY		\$ 59.00	\$ 59.00
03	REAR BUMPER SIDE BRACKET RH	1	NECESSARY		\$ 59.00	\$ 59.00
04	REAR BUMPER REINFORCEMENT	1	NOT NECESSARY		\$ 566.00	\$ -
05	REAR BUMPER REFLECTOR RH	1	CRACKED		\$ 84.00	\$ 84.00
06	END PANEL	1	REPAIR		\$ -	\$ -
					\$ 1,609.00	\$ 1,043.00
				Less 20%	\$ 321.80	\$ 208.60
					\$ 1,287.20	\$ 834.40

B) S/NETT ITEM

07	REAR BUMPER CLIP	1 SET	NECESSARY		\$ 40.00	\$ 30.00
08	REAR REVERSE SENSOR	1 SET	NOT NECESSARY		\$ 400.00	\$ -
					\$ 440.00	\$ 30.00

Parts Total :

\$ 1,727.20	\$ 864.40
--------------------	------------------

C) LABOUR CHARGES & MISC

09	CHECK REAR WIRING AND LIGHTNING SYSTEM				\$ 80.00	\$ 70.00
10	REMOVE AND RENEW REAR REVERSE SENSOR				\$ 120.00	\$ 100.00
11	DIAGNOIS CHECK AND CLEAR FAULT CODE				\$ 500.00	\$ 300.00
12	PANEL BEATING ON AFFECTED AREAS				\$ 700.00	\$ 600.00
13	SPRAY PAINTING ON AFFECTED AREAS				\$ 600.00	\$ 500.00
14	APPLY ANTI RUST ON AFFECTED AREAS				\$ 120.00	\$ 100.00
15	TO REMOVE, BREAK SEAL AND RENEW REAR NUMBER PLATE SEAL				\$ 150.00	\$ 150.00
	Labour Total :				\$ 2,270.00	\$ 1,820.00

Total Parts and Laboure :

\$ 3,997.20	\$ 2,684.40
--------------------	--------------------

FINAL LUMP SUM ADJUSTMENT

\$ 2,150.00

POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$2,150.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully,
WG APPRAISAL SERVICES

Winson Goh
Automotive Appraiser

