



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 8039B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	841.00	815.00
1	REAR BUMPER SIDE BRACKET LH	NOT NECESSARY	59.00	-
1	REAR BUMPER SIDE BRACKET RH	NECESSARY	59.00	32.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	566.00	-
1	REAR BUMPER REFLECTOR RH	CRACKED	84.00	27.00
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-321.80	-174.80
			1,287.20	699.20
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	400.00	-
			440.00	30.00
LABOUR				
	CHECK REAR WIRING AND LIGHTNING SYSTEM.		80.00	30.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		120.00	30.00
	DIAGNOIS CHECK AND CLEAR FAULT CODE.	NOT NECESSARY	500.00	-
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF END PANEL.		700.00	250.00
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	250.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO REMOVE, BREAK SEAL AND RENEW REAR NUMBER PLATE SEAL.		150.00	120.00
			2,270.00	680.00
GRAND TOTAL			3,997.20	1,409.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CS3/LPC21004428/T1vf3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.