



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 613P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER LH (CONSISTENT)	DENTED	788.50	788.50
1	FRONT DOOR LH (CONSISTENT)	DENTED	1,588.20	1,588.20
1	FRONT DOOR OUTER GARNISH (CONSISTENT)	DEFORMED	580.30	580.30
1	REAR SLIDING DOOR LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,855.20	-
1	REAR SLIDING DOOR OUTER GARNISH (CONSISTENT)	TO REPAIR SEE LABOUR	512.50	-
	LESS 25% DISCOUNT		-1,331.18	-739.25
			3,993.52	2,217.75
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT DOOR OUTER GARNISH CLIPS (SN)	NECESSARY	22.00	22.00
1	SET SLIDING DOOR OUTER GARNISH CLIPS (SN)	NOT NECESSARY	22.00	-
			44.00	22.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR SLIDING DOOR LH AND REAR SLIDING DOOR OUTER GARNISH.		1,000.00	500.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	700.00
	TUFF COAT.		180.00	50.00
	WIRING CHECK.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIX FRONT DOOR MECHANISM .		100.00	80.00
	TO REMOVE AND REFIX REAR DOOR MECHANISM .	NOT NECESSARY	120.00	-
			2,550.00	1,330.00
	<b>GRAND TOTAL</b>		<b>6,587.52</b>	<b>3,569.75</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,850.00</b>

Report Ref No. CC4/ASM21008628/Ags3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.