

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008630/AUCN2**Date:** 13/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00003292100
Claimant Vehicle No :	GBK4155D	Insured Vehicle No :	GBE1667U
Date of Loss:	02/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204297/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK4155D	Engine No:	1KDB036010
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHT02P000250513
Reg. Date:	21/07/2020 (Man. Year: 2020)	Odometer:	67408 km
Colour:	Grey		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Sailwin 6 mm	Rear Left Side:	Sailwin 6 mm
Front Right Side:	Sailwin 6 mm	Rear Right Side:	Sailwin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,903.20	3,523.00	7,380.20	67.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,160.00	2,220.00	65.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,283.20	4,683.00	9,600.20	67.21
Approved Total (Overridden) (\$\$)		3,700.00		
(\$\$)	14,283.20	3,700.00	10,583.20	74.10
+ GST 7.00/7.00% (\$\$)	999.82	259.00	740.82	74.10
Nett Amount (\$\$)	15,283.02	3,959.00	11,324.02	74.10

INSPECTION

Date of Assignment:	17/08/2021	
Date Inspected:	18/08/2021 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Sep 2021)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK4155D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	845.00 FL	*- FL
2	2		*BONNET HINGE	Not Necessary	336.00 FL	*- FL
3	2		*HEADLAMP	Cracked	1,284.00 FL	*1,284.00 FL
4	2		*HEADLAMP BRACKET	Not Necessary	130.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	652.00 FL	*652.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	372.00 FL	*372.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Deformed	154.00 FL	*154.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	586.00 FL	*374.00 FL
9	1		*FRONT BUMPER BEAM	Bent	215.00 FL	*215.00 FL
10	1		*FRONT WIPER GARNISH	Not Necessary	682.00 FL	*- FL
11	1		*FRONT WIPER GARNISH TOP SEAL	Not Necessary	65.00 FL	*- FL
12	1		*FRONT GRILLE BASE	Cracked	685.00 FL	*450.00 FL
13	1		*FRONT TOP GRILLE	Cracked	215.00 FL	*215.00 FL
14	1		*FRONT LOWER GRILLE	Cracked	248.00 FL	*248.00 FL
15	1		*FRONT DOOR RH	Not Necessary	1,987.60 FL	*- FL
16	2		*FRONT DOOR HINGE RH	Not Necessary	204.00 FL	*- FL
17	1		*FRONT DOOR CHECK RH	Not Necessary	154.00 FL	*- FL
18	1		*FRONT DOOR INNER LOCK RH	Not Necessary	317.00 FL	*- FL
19	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	46.00 FL	*- FL
20	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	298.00 FL	*- FL
21	1		*FRONT DOOR LOWER RUBBER RH	Not Necessary	165.00 FL	*- FL
22	1		*FRONT DOOR LOWER STEP PANEL RH	Not Necessary	358.00 FL	*- FL
23	1		*FRONT WHEEL COWLING RH	Not Necessary	214.00 FL	*- FL
24	1		*AIR CLEANER BOX	Not Necessary	685.00 FL	*- FL
25	1		*FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
26	1		*FRONT GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
27	1		*FRONT DOOR LOWER STEP GARNISH CLIP	Not Necessary	40.00 FS	*- FS
28	1		*FRONT DOOR COMPANY LETTERING	Not Necessary	90.00 FS	*- FS
29	1		*CAR BODY STICKER	Necessary	2,500.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,627.60	4,514.00
- List Item Discount on L Items 25.00/25.00% (\$)	2,724.40	991.00
Total Parts (\$)	10,903.20	3,523.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,200.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	100.00	30.00
4	WIRING CHECK	New	80.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
6	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	300.00	0.00
7	REMOVE AND REFIX FRONT DOOR PARTS	New	200.00	0.00
8	REFOCUS HEADLAMP BEAM	New	200.00	0.00
Gross Labour Cost (\$\$)			3,380.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >