

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21008631/ERA3Q2**Date:** 11/05/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0002152_02

Claimant Vehicle No : YP2678B **Insured Vehicle No :** GBE1658X

Date of Loss: 07/08/2021 Nature of Claim: TP Claim No: MFL2021D0003515

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP2678B**

Make & Model: ISUZU NPR85UH5A, 3.0 D (M) Engine No: 4JJ12K9545

Reg. Date: 17/05/2016 (Man. Year: 2016) Chassis No: JAANPR85HG7100202

Colour: White Odometer: 112480 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R16 Rear Tyre Size: 195/85 R16

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,990.00	1,713.60	276.40	13.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,030.00	420.00	28.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,440.00	2,743.60	696.40	20.24
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	3,440.00	2,200.00	1,240.00	36.05
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,707.45		

INSPECTION

Date of Assignment: 17/08/2021

Date Inspected: 18/08/2021 Inspected At: Ngee Ngee Motor
Block K, No. 22 Pandan Road
Singapore 128240

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jan 2022)	
Parts:	N/A	ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP2678B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*RH/LH SIDE LAMP ASSY	Broken	270.00 F	*270.00 FL
2	1		*RH HEAD ASSY	Cut	450.00 F	*450.00 FL
3	1		*FRONT PANEL	Dented	780.00 F	*750.00 FL
4	1		*FRONT GRILLED	Cut	450.00 F	*414.00 FL
5	8		*FRONT GRILLED CLIP	Necessary	40.00 F	*20.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	1,990.00 1,904.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 190.40
					Total Parts (\$\$)	1,990.00 1,713.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WELDING AND CUT FRONT PANEL AND REPLACE FRONT PANELAND REALIGNMENT FRONT BODY AND FIX LIGHTING SYSTEM	New	850.00	600.00
2	REPRAYING AREA	New	550.00	400.00
3	LABOUR CHARGE FOR LIGHTING SYSTEM	New	50.00	30.00
Gross Labour Cost (\$\$)			1,450.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >