#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21008641/R1TF3E2

**Date:** 13/09/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993611

Claimant Vehicle

CNAMAZONA

CNA

No: SMN172J Insured Vehicle No: SMN1389U

Date of Loss: 17/08/2021 Nature of Claim: TP Claim No: 1846126647SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMN172J

Make & Model: VOLKSWAGEN GOLF, 2.0 GTI (A) Engine No: CHH306270

Reg. Date: 23/07/2019 (Man. Year: 2019) Chassis No: WVWZZZAUZKW124918

Colour: Grey Odometer: 26095 km

Engine Capacity: 1984 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 17/08/2021

Date Inspected: 07/09/2021 Inspected At: 160 Sin Ming Drive #05-17 Repairer: Hiap Lek Automobile Trading

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$152,000.00 (EST)

## **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER	Repair	0.00 F	*- F
2	1	*FRT LH FENDER	Bent	0.00 F	*- F
3	1	*FRT LH FENDER EMBLEM	Necessary	0.00 F	*- F
4	1	*FRT LH WHEEL RIM	Scratched	0.00 F	*- F
F=Fra	anchise part.		Total Parts (S\$)	0.00	0.00
		Report was unsubmit	ted during this print-out.		

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >