

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21008647/BVF3E2

**Date:** 25/08/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070056768
<b>Claimant Vehicle No :</b>	SNB9119G	<b>Insured Vehicle No :</b>	SMT1339H
Date of Loss:	15/08/2021	Nature of Claim:	TP
		Claim No:	5587869561SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNB9119G</b>	Engine No:	30279292B37D15A
Make & Model:	BMW 116D, 1.5 D 5DR HATCH LED (A)	Chassis No:	WBA1V720205C06824
Reg. Date:	13/08/2015 (Man. Year: 2015)	Odometer:	84955 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	18/08/2021		
Date Inspected:	18/08/2021	Inspected At:	Kum Chew Motor Workshop (HQ) 160 Sin Ming Drive #05-08 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	5.0 days		

**Adjuster:** Lim Teow Guan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$51,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Broken	0.00 F	*- F
2	1		*REAR BUMPER	Dented	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
5	2		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
6	1		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
7	1		*REAR END PANEL	Dented	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
9	1		*TAILGATE	Dented	0.00 F	*- F
10	2		*TAILGATE LAMP	Broken	0.00 F	*- F
11	2		*REAR EXHAUST PIPE TIP	Bent	0.00 F	*- F
12	1		*TAILGATE ANTENNA	Broken	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >