



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6998G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER-RR BUMPER	CRACKED	459.40	459.40
1	MOULDING ASSY-RR BUMPER C	CRACKED	451.25	451.25
1	CAP-RR HOOK	MISSING	98.80	98.80
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	BEAM-RR BUMPER	NOT NECESSARY	394.80	-
	LESS 20% DISCOUNT		-285.25	-206.29
			1,141.00	825.16
<u>NETT ITEMS</u>				
1	REVERSE SENSOR ASSY (N)	NECESSARY	180.00	180.00
1	VEHICLE NUMBER PLATE REAR (N)	NOT NECESSARY	50.00	-
	LESS 10% DISCOUNT		-23.00	-18.00
			207.00	162.00
<u>LABOUR</u>				
	PANEL BEATING.		400.00	350.00
	SPRAYPAINT CHARGE.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			780.00	630.00
GRAND TOTAL			2,128.00	1,617.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,300.00

Report Ref No. NS/INC21008654/T1vce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.