

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21008660/R1ES3Q2**Date:** 15/11/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SKL7829L	<b>Insured Vehicle No :</b>	SLS9308L
Date of Loss:	11/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003405

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKL7829L</b>	Engine No:	K24W72012471
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Chassis No:	JHMRC1890GC205304
Reg. Date:	22/07/2016 (Man. Year: 2016)	Odometer:	87504 km
Colour:	Grey		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,547.25	2,892.86	654.39	18.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,530.00	5,455.00	2,075.00	27.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,077.25</b>	<b>8,347.86</b>	<b>2,729.39</b>	<b>24.64</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>775.41</b>	<b>584.35</b>	<b>191.06</b>	<b>24.64</b>

<b>Nett Amount (S\$)</b>	<b>11,852.66</b>	<b>8,932.21</b>	<b>2,920.45</b>	<b>24.64</b>
<b>+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		898.80		
<b>Nett Liability (S\$)</b>		<b>9,831.01</b>		

INSPECTION

Date of Assignment: 18/08/2021

Date Inspected: 18/08/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Kah Motor Co Sdn Bhd (HQ)  
6A MANDAI ESTATE, SINGAPORE 729903  
Singapore 729903

---

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2021)
<b>Parts:</b> M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKL7829L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SET,R.RR OUTSIDE	Bent	747.97 FS	*747.97 FS
2	1		*RUBBERRR QTR W/SHIELD (2 PCS)	Necessary	15.45 FS	*15.45 FS
3	1		*SEALR,QUARTER GLASS	Necessary	28.12 FS	*28.12 FS
4	1		*CLIP AQTR	Necessary	2.40 FS	*2.40 FS
5	1		*CLIPQUARTER WINDSHIELD A	Necessary	3.07 FS	*3.07 FS
6	1		*CLIPL	Necessary	3.07 FS	*3.07 FS
7	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
8	1		*MOLDING ASSYR,QTR WINDSHIELD	Necessary	87.75 FS	*87.75 FS
9	1		*PANEL COMPR SLIDE DOOR	Bent	800.25 FS	*800.25 FS
10	1		*GARNISH ASSYR.SLIDE DOOR LWR	Necessary	217.57 FS	*217.57 FS
11	1		*GARNISHR.RR.SLIDE DOOR PILLAR	Serviceable	36.82 FS	*- FS
12	1		*FENDERR.RR.INNER	Serviceable	93.00 FS	*- FS
13	1		*STRAKER RR	Missing	9.67 FS	*9.67 FS
14	1		*FACERR.BUMPER	Repair	454.57 FS	*- FS
15	1		*DISK ALUMINIUM WHEEL 17X7J	Scratched	731.77 FS	*731.77 FS
16	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
17	1		*TAPESLIDE DR REFLECTOR	Necessary	4.05 FS	*4.05 FS
18	1		*TAPE SETR.RR.DOOR SASH INNER	Necessary	45.67 FS	*45.67 FS
19	1		*MOLDING SLIDE DOOR RETAINER	Necessary	77.25 FS	*77.25 FS
20	1		*GARNISH ASSY R.WHEEL ARC	Missing	28.80 FS	*28.80 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**
**3,547.25**
**2,892.86**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REVERSE SENSORS	New	150.00	80.00
2	REMOVE & TRANSFER ITEMS TO NEW RR R DR ADJUST	New	650.00	325.00
3	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
4	REPLACE RR R QTR GLASS	New	350.00	280.00
5	REMOVE & INSTALL REAR SEAT COMPARTMENT LININGS	New	650.00	650.00
6	BODY JOINT SEALANT	New	100.00	80.00
7	CUT & RENEW RR R FENDER STRAIGHTEN INNER PANEL	New	2,500.00	1,950.00
8	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,500.00	1,560.00
9	WHEEL ALIGNMENT	New	180.00	180.00
			<b>Gross Labour Cost (\$\$)</b>	<b>7,530.00</b>
				<b>5,455.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >