

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21008665/GVCN2**Date:** 02/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00117302000

**Claimant Vehicle No :** GBK7080R **Insured Vehicle No :** SMP6905L

Date of Loss: 16/08/2021 Nature of Claim: TP Claim No: SNM21D204554/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBK7080R**

Make & Model: TOYOTA HIACE, 2.8 D DX (A) Engine No: 1GD8605955

Reg. Date: 29/10/2020 (Man. Year: 2020) Chassis No: GDH2011047702

Colour: White Odometer: 29173 km

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195R15 Rear Tyre Size: 195R15

Front Left Side: APLUS 6 mm Rear Left Side: APLUS 6 mm

Front Right Side: APLUS 6 mm Rear Right Side: APLUS 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,660.85	1,822.20	838.65	31.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	980.00	430.00	30.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,070.85</b>	<b>2,802.20</b>	<b>1,268.65</b>	<b>31.16</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,200.00</b>		
<b>Nett Amount (\$\$)</b>	<b>4,070.85</b>	<b>2,200.00</b>	<b>1,870.85</b>	<b>45.96</b>

**INSPECTION**

Date of Assignment: 19/08/2021

Date Inspected: 18/08/2021 Inspected At: AB ENGINEERING PTE LTD (HQ)  
25 SENANG CRESCENT, SINGAPORE 416598  
Singapore 416598

Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2021)
<b>Parts:</b>	213	TOYOTA HIACE 2.8 D DX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBK7080R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Buckled	2,035.20 FL	*1,785.00 FL
2	1		*TAIL GATE LOCK	Not Necessary	276.60 FL	*- FL
3	1		*TAIL GATE EMBLEM	Necessary	72.20 FL	*61.10 FL
4	1		*REAR BUMPER	Deformed	430.90 FL	*430.90 FL
5	2		*REAR BUMPER BRACKET	Not Necessary	66.80 FL	*- FL
6	1		*REVERSE SENSOR	Not Necessary	490.80 FL	*- FL
7	1		*STICKER HIACE	Necessary	45.00 FL	*35.80 FL
8	1		*STICKER 1200 KG	Necessary	50.30 FL	*36.80 FL
9	1		*STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
10	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,527.80</b>	<b>2,409.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	866.95	587.40
<b>Total Parts (\$\$)</b>	<b>2,660.85</b>	<b>1,822.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	30.00	0.00
2	TO DISMANTLE AND REFIX THE REAR WINDSCREEN GLASS TO THE NEW TAIL GATE	New	150.00	120.00
3	TO DISMANTLE AND REPLACE THE REVERSE SENSOR,RESET OF SAME	New	80.00	40.00
4	TO LABOUR CHARGE FOR REMOVE AND REPLACE OF THE ABOVE MENTIONED PARTS.TO DISMANTLE AND REFIT THE TAIL GATE FITTINGS TO THE NEW TAIL GATE;INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR AND RESHAPE OF THE END PANEL,ETC	New	650.00	450.00
5	TO PUTTY AND SPRAY PAINTING ON THE TAIL GATE INNER AND OUTER,END PANEL,INCLUDING TO APPLY RUSTPROOFING	New	500.00	370.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,410.00</b>	<b>980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >