

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008667/KVCN2**Date:** 30/09/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00005792000

**Claimant Vehicle
No :** SMQ5868L**Insured
Vehicle No :** SLS9055R

Date of Loss: 13/08/2021

Nature of Claim: TP

Claim
No: SNM21D204570/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMQ5868L**

Make & Model: RENAULT SCENIC, 1.6 (A)

Engine No: K9KF649D060222

Reg. Date: 26/11/2019 (Man. Year: 2019)

Chassis No: VF1RFA00962894815

Colour: Metallic Red

Odometer: 76355 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R20

Rear Tyre Size: 195/55R20

Front Left Side: Tourador 8 mm

Rear Left Side: Tourador 8 mm

Front Right Side: Tourador 8 mm

Rear Right Side: Tourador 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,612.64	1,523.17	11,089.47	87.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	575.00	3,415.00	85.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,602.64	2,098.17	14,504.47	87.36
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	16,602.64	1,650.00	14,952.64	90.06
+ GST 7.00/7.00% (S\$)	1,162.18	115.50	1,046.68	90.06
Nett Amount (S\$)	17,764.82	1,765.50	15,999.32	90.06

INSPECTION

Date of Assignment: 18/08/2021

Date Inspected: 13/09/2021

Inspected At:

Munich Autocare Pte Ltd (HQ)
60 Jalan Lam Huat, #06-43
Singapore 737869

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2021)
Parts:	M1-MPV	RENAULT SCENIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ5868L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE ASSY	Repair	2,247.42 F	*- FL
2	1	*REAR TAILGATE PANEL	Serviceable	750.52 F	*- FL
3	1	*REAR TAIL GATE STRIP	Serviceable	413.40 F	*- FL
4	1	*LETTERING RENAULT	Not Necessary	129.60 F	*- FL
5	1	*LETTERING SCENIC	Not Necessary	151.44 F	*- FL
6	1	*REAR VIEW CAMERA	Serviceable	707.88 F	*- FL
7	1	*STRIKER TRUNK DOOR	Serviceable	96.72 F	*- FL
8	1	*REAR BUMPER ASSY	Cracked	1,152.96 F	*1,152.96 FL
9	1	*REAR LOWER BUMPER	Dented/Cut	492.78 F	*492.78 FL
10	1	*REAR LOWER BUMPER,SILVER MOULDING	Serviceable	696.24 F	*- FL
11	4	*REVERSE SENSOR	Serviceable	1,021.44 F	*- FL
12	1	*BLIND SPOT SENSOR LH	Serviceable	457.92 F	*- FL
13	1	*REAR BUMPER HARDNESS	Serviceable	224.00 F	*- FL
14	1	*REAR BUMPER RETAINER RH	Serviceable	288.96 F	*- FL
15	1	*REAR BUMPER RETAINER LH	Serviceable	288.96 F	*- FL
16	1	*REAR BUMPER BRACKET CENTER	Serviceable	357.84 F	*- FL
17	1	*REAR BUMPER REINFORCEMENT	Repair	685.68 F	*- FL
18	2	*REAR BUMPER LOWER BRACKET CENTER	Repair	264.00 F	*- FL
19	1	*REAR BUMPER LOWER BRACKET LH	Repair	142.00 F	*- FL
20	1	*REAR BUMPER LOWER BRACKET RH	Repair	142.00 F	*- FL
21	1	*REAR BUMPER LOWER REFLECTOR LH	Serviceable	539.76 F	*- FL
22	1	*REAR BUMPER LOWER REFLECTOR RH	Serviceable	539.76 F	*- FL
23	1	*REAR END PANEL	Repair	421.92 F	*- FL
24	6	*REAR BUMPER CLIPS	Necessary	42.00 FS	*42.00 FS
25	1	*NUMBER PLATE WITH CASING	Serviceable	60.00 FS	*- FS
26	1	*SET REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Not Necessary	100.00 FS	*- FS
27	1	*REAR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
28	6	*SET REAR TAIL GATE OUTER GARNISH CLIPS	Not Necessary	42.00 FS	*- FS
29	6	*REAR TAIL GATE RIVET	Not Necessary	55.44 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,612.64	1,687.74
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	164.57
Total Parts (\$\$)	12,612.64	1,523.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING,REALIGN DISMANTLE REAR BUMPER,END PANEL OUTER AND ALL NECESSARY ETC	New	1,800.00	250.00
2	TO CHECK WIRING FOR PROPER FUNCTION	New	150.00	15.00
3	TO DISMANTLE & RENEW REVERSE SENSOR	New	280.00	60.00
4	TO APPLY TUFF COATING	New	180.00	0.00
5	TO REMOVE & INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	380.00	0.00
6	TO PUTTY & RESPRAY PAINTING REAR BUMPER,END PANEL AND ALL NECESSARY ETC	New	1,200.00	250.00
Gross Labour Cost (\$\$)			3,990.00	575.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >