

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008669/UVCN2**Date:** 15/10/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00127502000

Claimant Vehicle No : SDE7030T **Insured Vehicle No :** GQ8998X

Date of Loss: 15/08/2021 Nature of Claim: TP Claim No: SNM21D204531/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDE7030T**

Make & Model: HONDA CIVIC, 1.5 (A) Engine No: R16B25520799

Reg. Date: 16/03/2021 (Man. Year: 2021) Chassis No: MRHFC5650LT000579

Colour: Grey Odometer: 12968 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55R16 Rear Tyre Size: 215/55R16

Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,924.27	1,535.44	1,388.83	47.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,430.00	7,150.00	2,280.00	24.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,354.27	8,685.44	3,668.83	29.70
+ GST 7.00/7.00% (S\$)	864.80	607.98	256.82	29.70
Nett Amount (S\$)	13,219.07	9,293.42	3,925.65	29.70

INSPECTION

Date of Assignment: 18/08/2021

Date Inspected: 23/08/2021 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2021)
Parts: 143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDE7030T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY,RR BUMPER	Dented	462.90 FS	*462.90 FS
2	1		*GARNISH ASSY,RR BUMPER LOWER	Deformed	96.37 FS	*96.37 FS
3	1		*SPACERR.RR BUMPER SIDE	Not Necessary	8.62 FS	*- FS
4	1		*SPACERL.RR BUMPER SIDE	Not Necessary	8.62 FS	*- FS
5	1		*CLIP,BUMPER (7 Pcs)	Necessary	12.07 FS	*12.07 FS
6	1		*BEAM COMPRR BUMPER	Dented	141.00 FS	*141.00 FS
7	1		*PANEL SETRR	Dented	208.12 FS	*208.12 FS
8	1		*STIFFENER,R.RR PANEL SIDE	Necessary	22.87 FS	*22.87 FS
9	1		*STIFFENERL.RR PANEL SIDE	Necessary	22.87 FS	*22.87 FS
10	1		*LID COMP TRUNK	Dented	416.17 FS	*416.17 FS
11	1		*WEATHERSTRIP TRUNK LID	Not Necessary	52.50 FS	*- FS
12	1		*GARNISH ASSYRR.LICENSE	Repair	86.10 FS	*- FS
13	1		*LOCK ASSYTRUNK	Not Necessary	63.67 FS	*- FS
14	1		*LINING ASSYRR PANEL	Not Necessary	37.72 FS	*- FS
15	1		*EMBLEM SETRR	Necessary	10.05 FS	*10.05 FS
16	1		*EMBLEMRR	Necessary	9.37 FS	*9.37 FS
17	1		*EMBLEM.H-MARK	Necessary	10.50 FS	*10.50 FS
18	1		*NUTPUSH 3MM (2 Pcs)	Necessary	3.15 FS	*3.15 FS
19	1		*TAILLIGHT ASSYR	Not Necessary	223.80 FS	*- FS
20	1		*BUZZER ASSYSMART	Not Necessary	49.05 FS	*- FS
21	1		*ANTENNA ASSYL.F	Not Necessary	47.40 FS	*- FS
22	1		*CAMERA ASSY RR VI	Not Necessary	270.15 FS	*- FS
23	4		*SENSOR ASSY,PARKING	Serviceable	466.20 FS	*- FS
24	1		*NUMBER PLATE WITH CASING-L	Serviceable	45.00 FS	*- FS
25	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
26	1		*BODY JOINT SEALANT	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,924.27	1,535.44
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	180.00	120.00
2	BODY UNDERSIDE COATING	New	100.00	100.00
3	APPLY BODY UNDERSIDE COATING	New	250.00	200.00
4	REMOVE & INSTALL REVERSE SENSORS-4 PCS	New	200.00	130.00
5	REMOVE & INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	350.00
6	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
7	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	350.00
8	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	450.00	350.00
9	CUT OFF & RENEW RR PANEL.STRAIGHTEN ALIGN	New	3,300.00	2,600.00
10	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,400.00	2,600.00
			Gross Labour Cost (\$\$)	9,430.00
				7,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >