

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21008671/KQF3N2**Date:** 14/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210025990
Claimant Vehicle No :	SMU9226S	Insured Vehicle No :	SGM1635K
Date of Loss:	16/08/2021	Nature of Claim:	TP
		Claim No:	0709033818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU9226S	Engine No:	L15B6022287
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK82101933
Reg. Date:	28/08/2020 (Man. Year: 2019)	Odometer:	14820 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,116.53	17,102.48	8,014.05	31.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,785.00	3,700.00	2,085.00	36.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,901.53	20,802.48	10,099.05	32.68
Approved Total (Overridden) (S\$)		16,900.00		
Nett Amount (S\$)	30,901.53	16,900.00	14,001.53	45.31

INSPECTION

Date of Assignment:	18/08/2021		
Date Inspected:	19/08/2021	Inspected At:	Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	14.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,305.10 FL	*1,021.50 FL
2	1		*FRONT BONNET HINGE	O/s Distorted	190.20 FL	*95.10 FL
3	1		*FRONT BONNET LOCK	Distorted	165.10 FL	*165.10 FL
4	1		*FRONT BONNET INSULATOR	Serviceable	146.20 FL	*- FL
5	1		*FRONT WIPER GARNISH	Cracked	195.10 FL	*195.10 FL
6	1		*FRONT FENDER	O/s Buckled	1,100.20 FL	*511.60 FL
7	2		*FRONT HEADLAMP ASSY	O/s Cracked/N/s Mtg Cracked	4,545.40 FL	*4,545.40 FL
8	1		*FRONT HEADLAMP LOWER BRACKET	O/s Cracked	310.20 FL	*155.10 FL
9	1		*FRONT GRILLE	Cracked	283.70 FL	*283.70 FL
10	1		*FRONT GRILLE CHROME	Cracked	235.10 FL	*235.10 FL
11	1		*FRONT GRILLE EMBLEM	Necessary	55.70 FL	*55.70 FL
12	1		*FRONT GRILLE LOWER CHROME MOULDING	Dented	165.70 FL	*165.70 FL
13	1		*FRONT BUMPER	Bent	925.70 FL	*925.70 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	385.20 FL	*385.20 FL
15	1		*FRONT BUMPER SIDE RETAINER	O/s Distorted	150.20 FL	*75.10 FL
16	1		*FRONT BUMPER LOWER GRILLE	Cracked	186.70 FL	*186.70 FL
17	1		*FRONT BUMPER TOW COVER	Necessary	45.60 FL	*45.60 FL
18	1		*FRONT FOG LAMP CHROME GARNISH	O/s Dented	389.80 FL	*194.90 FL
19	2		*FRONT FOG LAMP	Serviceable	1,242.20 FL	*- FL
20	1		*FRONT SUPPORT PANEL	Bent	631.20 FL	*631.20 FL
21	1		*FRONT SUPPORT PANEL TOP GARNISH	Dented	95.70 FL	*95.70 FL
22	1		*FRONT O/S CHASSIS	Repair	405.80 FL	*- FL
23	1		*FRONT CHASSIS BRACKET	O/s Bent	375.00 FL	*187.50 FL
24	1		*AIR CON CONDENSER	Punctured	887.30 FL	*887.30 FL
25	1		*RADIATOR	Punctured	1,483.10 FL	*1,483.10 FL
26	1		*RADIATOR FAN ASSY	Serviceable	875.10 FL	*- FL
27	1		*AIR CON FAN ASSY	Serviceable	955.10 FL	*- FL
28	1		*FRONT WINDSCREEN WASHER TANK	Dented	85.70 FL	*85.70 FL
29	1		*REAR TAIL-GATE ASSY	Bent	1,281.10 FL	*1,193.40 FL
30	1		*REAR TAIL-GATE ASSY MOULDING	Necessary	95.10 FL	*95.10 FL
31	1		*REAR WIPER MOTOR	Jammed	485.10 FL	*485.10 FL
32	1		*REAR TAIL-GATE OUTER GARNISH	Serviceable	205.10 FL	*- FL
33	1		*REAR TAIL-GATE EMBLEM SHUTTLE	Necessary	45.10 FL	*45.10 FL
34	1		*REAR TAIL-GATE EMBLEM H	Not Necessary	40.10 FL	*- FL
35	1		*REAR TAIL-GATE OUTER CHROME GARNISH	Serviceable	385.70 FL	*- FL
36	1		*REAR TAIL-GATE INNER LOCK	Dented	305.10 FL	*305.10 FL
37	1		*REAR TAIL-GATE INNER TRIM BOARD	Dented/Mtg Cracked	387.40 FL	*387.40 FL
38	1		*REAR TAIL-GATE POCKET HANDLE	Serviceable	45.10 FL	*- FL
39	1		*REAR TAIL-GATE REFLECTOR	O/s Dented	971.40 FL	*425.00 FL
40	1		*REAR TAIL-LAMP	O/s Dented	914.20 FL	*457.10 FL
41	2		*REAR TAIL-LAMP PANEL	Repair	570.21 FL	*- FL
42	1		*REAR BOOT RUBBER	Dented/Cut	195.70 FL	*195.70 FL
43	2		*REAR FENDER INNER TRIM BOARD	Mtg Cracked	970.40 FL	*970.40 FL
44	1		*REAR END PANEL	Bent	685.10 FL	*631.50 FL
45	1		*REAR END PANEL INNER GARNISH	Buckled	185.90 FL	*185.90 FL
46	1		*REAR END PANEL LOWER COVER	Serviceable	87.10 FL	*- FL
47	1		*REAR BUMPER	Bent	965.70 FL	*965.70 FL
48	1		*REAR BUMPER TOW COVER	Dented	48.20 FL	*48.20 FL
49	1		*REAR BUMPER CENTER CHROME MOULDING	Dented	85.60 FL	*85.60 FL
50	1		*REAR BUMPER SIDE RETAINER	O/s Distorted	76.40 FL	*38.20 FL
51	2		*REAR BUMPER REFLECTOR	Serviceable	310.40 FL	*- FL
52	2		*REAR BUMPER REFLECTOR GARNISH	No such part	213.40 FL	*- FL
53	2		*REAR BUMPER REFLECTOR SPONGE	Serviceable	164.20 FL	*- FL
54	1		*REAR TOW COVER	Repeated	35.10 FL	*- FL
55	1		*RADIO ANTENNA	Dented	125.60 FL	*125.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR SPARE TYRE PANEL	Bent	1,072.50 FL	*1,072.50 FL
57	1		*REAR SPARE TOOL CONSOLE BOX	Distorted	205.60 FL	*205.60 FL
58	1		*REAR BOOT TOP COVER BOARD	Buckled	297.10 FL	*297.10 FL
59	1		*REAR EXHAUST SILENCER	Repair	855.10 FL	*- FL
60	4		*REAR REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
61	1		*REAR REVERSE CAMERA	Serviceable	300.00 FS	*- FS
62	1		*REAR TAIL-GATE GLASS SEALANT	Necessary	55.00 FS	*40.00 FS
63	20		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
64	1		*REAR NO PLATE	Serviceable	40.00 FS	*- FS
65	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
66	1		*FRONT BONNET EDGE LINING	Necessary	120.00 FS	*60.00 FS
67	1		*REAR TAIL-GATE EDGE LINING	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	31,141.91	21,268.10
- List Item Discount on L Items 20.00/20.00% (S\$)	6,025.38	4,165.62
Total Parts (S\$)	25,116.53	17,102.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	2,400.00	1,500.00
2	TO PUTTY AND SPRAY PAINT	New	2,000.00	1,600.00
3	CHECK & RECONNECT WIRING	New	45.00	40.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	150.00	120.00
5	REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	120.00	120.00
6	REMOVE/REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	150.00	60.00
7	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	100.00	100.00
8	REMOVE/RENEW REAR EXHAUST SILENCER	New	150.00	60.00
9	REMOVE/REFIT FUEL TANK TO FACILITATE REPAIR	New	150.00	0.00
10	REMOVE/RENEW AIR CON CONDENSER AND TO TOP UP GAS ELEMENT	New	180.00	100.00
11	TO STRAIGHTEN FRONT CHASSIS ALIGNMENT	New	280.00	0.00
12	CHECK AND REALIGN WHEEL ALIGNMENT	New	60.00	0.00
			Gross Labour Cost (\$\$)	3,700.00
			5,785.00	3,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >