

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21008672/EVCN2**Date:** 02/12/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00004112102

**Claimant Vehicle No :** GBG130Y **Insured Vehicle No :** XE316D

Date of Loss: 04/08/2021 Nature of Claim: TP Claim No: SNM21D204401/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG130Y**

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2695426

Reg. Date: 25/05/2017 (Man. Year: 2017) Chassis No: JTFAT35Y20K207884

Colour: Silver Odometer: 97745 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C

Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm

Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,253.30	5,543.47	1,709.83	23.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,510.00	1,820.00	6,690.00	78.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,763.30</b>	<b>7,363.47</b>	<b>8,399.83</b>	<b>53.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,900.00</b>		
<b>(S\$)</b>	15,763.30	5,900.00	9,863.30	62.57
<b>+ GST 7.00/7.00% (S\$)</b>	1,103.43	413.00	690.43	62.57
<b>Nett Amount (S\$)</b>	<b>16,866.73</b>	<b>6,313.00</b>	<b>10,553.73</b>	<b>62.57</b>

INSPECTION

Date of Assignment: 03/11/2021

Date Inspected: 03/11/2021 Inspected At: BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722 REPAIRER :MOVA AUTOMOTIVE PTE LTD

Estimated Period of Repair: 8.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 01 Dec 2021)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG130Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE	Dented	1,599.70 FL	*1,599.70 FL
2	1		*REAR GATE STICKER TOYOTA	Necessary	141.80 FL	*141.80 FL
3	1		*REAR GATE STICKER DYNA	Necessary	58.30 FL	*58.30 FL
4	1		*REAR GATE LOCK RH	Bent	171.30 FL	*171.30 FL
5	1		*REAR GATE LOCK CATCH RH	Jammed	101.50 FL	*101.50 FL
6	1		*REAR GATE HINGE (4 Pcs)	Bent (2 Pcs only)	390.40 FL	*195.20 FL
7	1		*REAR SIDE GATE RH	Dented	2,600.60 FL	*2,600.60 FL
8	6		*REAR SIDE GATE HINGES RH	Bent	585.60 FL	*585.60 FL
9	1		*REAR SIDE GATE CATCH RH	Jammed	217.30 FL	*217.30 FL
10	1		*REAR LAMP RH	Not Necessary	248.60 FL	*- FL
11	1		*R/R CABIN PANEL	Repair	675.30 FL	*- FL
12	1		*SIDE MIRROR LH BRACKET	Not Necessary	277.30 FL	*- FL
13	1		*SIDE MIRROR MOTOR LH	Not Necessary	696.70 FL	*- FL
14	1		*REAR RH UPPER RAILING	Dented	450.00 FS	*450.00 FS
15	1		*REAR GATE STICKER 70KM	Necessary	20.00 FS	*20.00 FS
16	1		*REAR GATE STICKER 13PAX	Necessary	20.00 FS	*20.00 FS
17	1		*REAR GATE ALUMINIUM BOARD	Dented	400.00 FS	*350.00 FS
18	1		*REAR SIDE GATE ALUMINIUM BOARD RH	Dented	500.00 FS	*450.00 FS
19	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,194.40</b>	<b>6,961.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,941.10	1,417.83
<b>Total Parts (\$\$)</b>	<b>7,253.30</b>	<b>5,543.47</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CUT & WELD CABIN END PILLAR RH.TO REPAIR CABIN BODY END PANEL,FLATBED CARRIAGE SIDE MEMBER.TO REMOVE & REFIX DAMAGED PARTS STRAIGHTEN & REALIGN AFFECTED AREAS	New	1,100.00	600.00
2	TO SPRAY REAR GATE,SIDE GATE,SIDE MEMBER,REAR MEMBER,REAR FLATBED CARRIAGE,CABIN END PANEL,CABIN SIDE PANEL RH AND AFFECTED AREAS	New	1,200.00	600.00
3	TO SUPPLY MATERIAL AND LABOUR TO REBUILD CANOPY TRUCK ROOFTOP CAN OPEN SIDE LIFT UP & DOWN WITH SLIDING CANVAS AND SLIDING DOOR	New	5,500.00	500.00
4	TO REMOVE & REFIX REAR FLATBED AND CABIN FOR ENABLE TO REPLACE CABIN SIDE PANEL AND REPAIR CABIN END PANEL	New	250.00	0.00
5	TO REMOVE & REFIX SAFETY BELT AND CUSHION CARPET AND OTHER ATTACHMENT PARTS	New	80.00	30.00
6	TO PROGRAMMING ADAS SYSTEM	New	180.00	30.00
7	TO RUST PROOF AFFECTED AREAS	New	100.00	30.00
8	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,510.00</b>	<b>1,820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >