

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21008673/DVF3N2**Date:** 06/05/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001752914
Claimant Vehicle No :	SHC2989Z	Insured Vehicle No :	FBS4174G
Date of Loss:	17/08/2021	Nature of Claim:	TP
		Claim No:	261322

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2989Z	Engine No:	G4LEKU406243
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU189232
Reg. Date:	13/02/2020 (Man. Year: 2019)	Odometer:	297664 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,993.40	5,425.52	7,567.88	58.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,590.00	1,730.00	3,860.00	69.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,583.40	7,155.52	11,427.88	61.50
+ GST 7.00/7.00% (S\$)	1,300.84	500.89	799.95	61.49
Nett Amount (S\$)	19,884.24	7,656.41	12,227.83	61.50

INSPECTION

Date of Assignment:	19/08/2021	
Date Inspected:	19/08/2021	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	7.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2022)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2989Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Bent	418.30 FL	*418.30 FL
2	1		*FRONT BUMPER MOULDING CENTRE UPPER	Not Necessary	368.50 FL	*- FL
3	1		*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	35.00 FL	*- FL
4	1		*FRONT BUMPER BRACKET (RH)	Not Necessary	28.00 FL	*- FL
5	1		*FRONT BUMPER RETAINER MOUNTING (RH)	Not Necessary	65.30 FL	*- FL
6	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
7	1		*FRONT BUMPER AIR DUCT (RH)	Not Necessary	153.80 FL	*- FL
8	1		*DAY LIGHT,RH	Not Necessary	642.50 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	949.30 FL	*949.30 FL
10	1		*HEADLAMP (RH)	Mounting Broken	3,987.30 FL	*2,396.00 FL
11	1		*FRONT FENDER (RH)	Dented	490.70 FL	*490.70 FL
12	1		*FRONT FENDER SHIELD (RH)	Serviceable	164.70 FL	*- FL
13	1		*FRONT WHEEL RIM (RH)	Bent/Distorted	1,124.20 FL	*1,124.20 FL
14	1		*FRONT WHEEL HUB CAP AND HUB ASSY (RH)	Not Necessary	678.50 FL	*- FL
15	1		*FRONT WHEEL HUB CAP	Cut/Bent	346.40 FL	*346.40 FL
16	1		*FRONT SHOCK ABSORBER (ASSY)(RH)	Not Necessary	372.50 FL	*- FL
17	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	372.50 FL	*- FL
18	1		*STG TIE ROD	Not Necessary	125.60 FL	*- FL
19	1		*STG TIE END	Not Necessary	94.70 FL	*- FL
20	1		*STABILIZER BAR	Not Necessary	326.80 FL	*- FL
21	1		*STABILIZER BAR LINK	Not Necessary	92.10 FL	*- FL
22	1		*FRONT SUSPENSION LOWER ARM (RH)	Not Necessary	596.80 FL	*- FL
23	1		*KNUCKLE ARM (RH)	Not Necessary	663.60 FL	*- FL
24	1		*REAR BUMPER	Repair	459.40 FL	*- FL
25	1		*REAR BUMPER SIDE RETAINER (RH)	Not Necessary	85.80 FL	*- FL
26	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
27	1		*TAIL LAMP (RH)	Broken	870.40 FL	*870.40 FL
28	1		*TAIL LAMP QUARTER PANEL (RH)	Not Necessary	208.90 FL	*- FL
29	1		*REAR FENDER (RH)	Repair	1,768.30 FL	*- FL
30	1		*REAR FENDER SHIELD REAR PIECE (RH)	Not Necessary	173.60 FL	*- FL
31	1		*REAR FENDER SHIELD FRT PIECE (RH)	Not Necessary	165.50 FL	*- FL
32	1		*EMBLEM-BLUE DRIVE (RH)	Necessary	26.60 F	*26.60 FN
33	1		*FRONT TYRE (RH)(50%)	Cut	216.00 FS	*108.00 FS
34	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	16,168.60	6,754.90
- List Item Discount on L Items 20.00/20.00% (S\$)	3,175.20	1,324.06
- Nett Item Discount on N Items 0.00/20.00% (S\$)	0.00	5.32
Total Parts (S\$)	12,993.40	5,425.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING CHARGE	New	1,600.00	800.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	0.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
10	RE-SET FRT ABS SYSTEM	New	200.00	0.00
11	REMOVE/REFIX RADIATOR	New	90.00	0.00
12	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
13	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
14	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR	New	550.00	0.00
Gross Labour Cost (\$\$)			5,590.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >