

ASS. FRY:

REF:

CC6/CTI21008674/Dpa³

ASSIGNMENT

CUE Mach 3228

From: _____ Date: _____

Estimated Cost: _____

OD / TP RES / DD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Work in m/s _____

of _____

Insured _____

Policy No. _____

Claims to _____

Sum Insured: _____


Excess: _____

(Check record)

Make of Car: _____

(Police Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen _____ Consistent? : Yes or No

Est. Repairs: 36 days Res.: Yes or NoLump Sum: PIP % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD4028DYr Regn: 2020 / March

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai IoniqC.D. 1580Colour: Blue

A/C: Insured / Std / N/A

Sp. Reading: 107360

T/Radio: Insured / Std / N/A

Eng/No: G4LEK U409090C/No: KMHCB851CVLU190013

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / Std / STD A/Rim or

Tyre Size: F: 195/65 R15R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUSA /

TOYO / YOKO or

Duratrax

Front

Rear

R/Bal: S mmR/Bal: S mmL/Bal: S mmL/Bal: S mmD.O.A. 17/08/2021D.O.L. 19/08/2021Survey held at Bjrost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China E-ping XE 7368-H

28/11/22 John PIP 667732 with 6 days of work

677 6722.32

Date/Time, File Pass to?

☐ : Prefl. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS: _____

Photos: _____

Add Fee: _____

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Insp (\$ _____)

Report Format: _____