

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG21008676/BUF3E2**Date:** 16/03/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001552783
<b>Claimant Vehicle No :</b>	SMK7251J	<b>Insured Vehicle No :</b>	GBE4748A
Date of Loss:	17/08/2021	Nature of Claim:	TP
		Claim No:	261333

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMK7251J</b>	Engine No:	4J11AC1864
Make & Model:	MITSUBISHI OUTLANDER, 2.0 CVT (A)	Chassis No:	GF7W0600565
Reg. Date:	23/04/2019 (Man. Year: 2018)	Odometer:	44991 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,146.38	6,078.00	7,068.38	53.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,590.00	1,460.00	47.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,196.38</b>	<b>7,668.00</b>	<b>8,528.38</b>	<b>52.66</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,100.00</b>		
<b>(\$\$)</b>	16,196.38	6,100.00	10,096.38	62.34
<b>+ GST 8.00/8.00% (\$\$)</b>	1,295.71	488.00	807.71	62.34
<b>Nett Amount (\$\$)</b>	<b>17,492.09</b>	<b>6,588.00</b>	<b>10,904.09</b>	<b>62.34</b>

INSPECTION

Date of Assignment:	19/08/2021	
Date Inspected:	19/08/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	7.0 days	

**Adjuster:** Lim Teow Guan**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2023)
<b>Parts:</b>	M1-SUV	MITSUBISHI OUTLANDER 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMK7251J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,089.00 FL	*989.00 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOUNTING	Necessary	86.00 FL	*86.00 FL
3	1		*TAILGATE OUTLANDER EMBLEM	Necessary	95.00 FL	*95.00 FL
4	1		*TAILGATE MIVEC EMBLEM	Necessary	42.00 FL	*42.00 FL
5	1		*TAILGATE CHROME GARNISH	Not Necessary	496.00 FL	*- FL
6	1		*TAILGATE CHROME GARNISH CENTRE EMBLEM	Not Necessary	57.00 FL	*- FL
7	1		*TAILGATE NUMBER PLATE LAMP	Not Damaged	37.80 FL	*- FL
8	1		*TAILGATE NUMBER PLATE LAMP	Not Damaged	37.80 FL	*- FL
9	1		*TAILGATE OPEN BUTTON SENSOR	Not Damaged	201.00 FL	*- FL
10	1		*TAILGATE RH LAMP ASSY	Not Necessary	506.00 FL	*- FL
11	1		*TAILGATE LH LAMP ASSY	Not Necessary	506.00 FL	*- FL
12	1		*TAILGATE INNER TRIM BOARD	Not Necessary	364.00 FL	*- FL
13	1		*TAILGATE LOCK	Jammed	477.00 FL	*450.00 FL
14	1		*TAILGATE LOCK CATCH	Not Damaged	23.00 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Not Damaged	213.00 FL	*- FL
16	1		*TAILGATE WIPER MOTOR	Not Damaged	437.00 FL	*- FL
17	1		*TAILGATE WIPER MOTOR BRACKET	Not Damaged	29.00 FL	*- FL
18	1		*TAILGATE WIPER ARM	Not Damaged	67.00 FL	*- FL
19	1		*TAILGATE RH SIDE LOCK SENSOR	No such part	428.00 FL	*- FL
20	1		*TAILGATE LH SIDE LOCK SENSOR	No such part	428.00 FL	*- FL
21	1		*TAILGATE RH DAMPER	Not Damaged	198.00 FL	*- FL
22	1		*TAILGATE LH DAMPER	Not Damaged	198.00 FL	*- FL
23	1		*TAILGATE PULL HANDLE	Not Damaged	32.00 FL	*- FL
24	1		*REAR BUMPER	Broken	811.00 FL	*811.00 FL
25	1		*REAR BUMPER PAD (BLACK)	Broken	292.00 FL	*292.00 FL
26	1		*REAR BUMPER LOWER (SILVER)	Broken	384.00 FL	*384.00 FL
27	1		*REAR BUMPER RH REFLECTOR ASSY	Not Necessary	103.00 FL	*- FL
28	1		*REAR BUMPER LH REFLECTOR ASSY	Not Damaged	103.00 FL	*- FL
29	1		*REAR BUMPER RH SIDE RETAINER	Necessary	18.00 FL	*18.00 FL
30	1		*REAR BUMPER LH SIDE RETAINER	Necessary	18.00 FL	*18.00 FL
31	1		*REAR BUMPER RH SIDE GARNISH	Not Damaged	106.00 FL	*- FL
32	1		*REAR BUMPER LH SIDE GARNISH	Not Damaged	106.00 FL	*- FL
33	1		*REAR BUMPER REINFORCEMENT RH BRACKET	Bent	64.00 FL	*64.00 FL
34	1		*REAR BUMPER REINFORCEMENT LH BRACKET	Bent	64.00 FL	*64.00 FL
35	1		*REAR BUMPER CENTRE BRACKET	No such part	43.00 FL	*- FL
36	1		*RH TAILLAMP ASSY	Broken	615.00 FL	*615.00 FL
37	1		*LH TAILLAMP ASSY	Broken	615.00 FL	*615.00 FL
38	1		*END PANEL	Dented	255.00 FL	*255.00 FL
39	1		*END PANEL INNER GARNISH	Broken	115.00 FL	*115.00 FL
40	1		*KEYLESS SENSOR	Not Damaged	96.00 FL	*- FL
41	1		*BUZZER SENSOR	Broken	91.00 FL	*91.00 FL
42	1		*REAR LH FENDER INNER TRIM BOARD	Broken	633.00 FL	*633.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR RH FENDER INNER TRIM BOARD	Broken	633.00 FL	*633.00 FL
44	1		*REAR COMPARTMENT PANEL CARGO BOX	Not Damaged	191.00 FL	*- FL
45	1		*REAR COMPARTMENT PANEL CARGO BOX COVER	Not Damaged	255.00 FL	*- FL
46	1		*SPARE TYRE CARRIAGE	Not Damaged	258.00 FL	*- FL
47	1		*EXHAUST SILENCER	Not Damaged	528.50 FL	*- FL
48	1		*EXHAUST SILENCER GASKET	Not Damaged	42.10 FL	*- FL
49	1		*TAILGATE C&C EMBLEM	Necessary	75.00 FS	*75.00 FS
50	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
51	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
52	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	70.00 FS	*- FS
53	1		*TAILGATE REVERSE CAMERA	Not Damaged	650.00 FS	*- FS
54	1		*REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
55	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS
56	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*20.00 FS
57	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*20.00 FS
58	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
59	1		*KEYLESS SENSOR	Repeated	96.00 FL	*- FL
60	1		*TAILGATE NUMBER PLATE GARNISH	Not Necessary	102.00 FL	*- FL
61	1		*TAILGATE RH NUMBER PLATE LAMP ASSY	Repeated	42.00 FL	*- FL
62	1		*TAILGATE LH NUMBER PLATE LAMP ASSY	Repeated	42.00 FL	*- FL
63	1		*TAILGATE PUSH BUTTON SENSOR	Repeated	199.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>14,443.20</b>	<b>6,705.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,296.82	627.00
<b>Total Parts (\$)</b>	<b>13,146.38</b>	<b>6,078.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	70.00	0.00
4	APPLY RUST PROOFING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
5	REMOVE, REPLACE AND REINSTALL TAILGATE WINDSCREEN GLASS AND SEALANTS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	100.00	60.00
7	REMOVE, REPLACE AND ADJUST TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	100.00	0.00
8	REMOVE AND REPLACE REAR INNER TRIMS, GARNISH AND BOARDS TO ASSIST REPAIR	New	280.00	150.00
9	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR TO ASSIST REPAIR	New	70.00	60.00
10	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,050.00</b>	<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >