

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21008678/KUF3E2

Date: 19/11/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD Policy No: 0999993598

Date of Loss: 01/08/2021

Nature of Claim: OD

Claim No: 6686224615SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ1651K**
Make & Model: MERCEDES-BENZ E250, 1.8 (A) Engine No: 27492031389300
Reg. Date: 25/04/2018 (Man. Year: 2018) Chassis No: WDD2130452A414492
Colour: Metallic Grey Odometer: 87773 km
Engine Capacity: 1991 cc
Market Value/New Car Price: S\$160,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45R18 Rear Tyre Size: 275/40R18
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,128.14	27,081.19	2,046.95	7.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,440.00	2,780.00	2,660.00	48.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,568.14	29,861.19	4,706.95	13.62
- Excess (S\$)	1,700.00	1,700.00	0.00	0.00
(S\$)	32,868.14	28,161.19	4,706.95	14.32
+ GST 7.00/7.00% (S\$)	2,300.77	1,971.28	329.49	14.32
Nett Amount (S\$)	35,168.91	30,132.47	5,036.44	14.32

INSPECTION

Date of Assignment: 18/08/2021

Date Inspected: 19/08/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS (WCP)	Cracked	850.00 F	*850.00 F
2	1		*ROOF LINING (WCP)	Deformed	1,120.00 F	*1,120.00 F
3	2		*WINDOW AIR BAG-RH/LH (WCP)	Burst	1,700.00 F	*1,700.00 F
4	1		*DASHBOARD ASSY (WCP)	Torn	2,480.00 F	*2,480.00 F
5	1		*STEERING AIR BAG (WCP)	Burst	1,880.00 F	*1,880.00 F
6	1		*PASSENGER AIR BAG (WCP)	Burst	1,280.00 F	*1,280.00 F
7	1		*KNEE AIR BAG (WCP)	Burst	850.00 F	*850.00 F
8	1		*AIRBAG CONTROL UNIT (WCP)	Necessary	680.00 F	*680.00 F
9	1		*AIRBAG SENSOR (WCP)	Necessary	155.00 F	*155.00 F
10	2		*FRONT SAFETY BELT-RH/LH (WCP)	Jammed	1,900.00 F	*1,900.00 F
11	2		*REAR SAFETY BELT-RH/LH (WCP)	Jammed	840.00 F	*840.00 F
12	1		*BONNET (WCP)	Bent	1,350.00 F	*1,350.00 F
13	1		*BONNET CENTRE LOGO (WCP)	Necessary	68.00 F	*68.00 F
14	1		*BONNET INSULATOR (WCP)	Not Necessary	198.00 F	*- F
15	2		*BONNET HINGE-RH/LH (WCP)	Not Necessary	270.00 F	*- F
16	1		*BONNET SPRING-LH (WCP)	Not Necessary	28.00 F	*- F
17	1		*BONNET LOCK-LH (WCP)	Not Necessary	62.00 F	*- F
18	1		*BONNET LOCK SWITCH-LH (WCP)	Not Necessary	45.00 F	*- F
19	1		*SUPPORT PANEL (WCP)	Buckled	650.00 F	*650.00 F
20	2		*HEADLAMP ASSY - RH / LH (WCP)	Mtg Cracked	3,960.00 F	*3,960.00 F
21	1		*HEADLAMP BRACKET - LH (WCP)	Cracked	65.00 F	*65.00 F
22	1		*FRONT GRILLE (WCP)	Cracked	165.00 F	*165.00 F
23	1		*FRONT GRILLE OUTER CHROME (WCP)	Cracked	190.00 F	*190.00 F
24	1		*FRONT GRILLE BEAM (WCP)	Cracked	225.00 F	*225.00 F
25	2		*FRONT GRILLE BEAM MOULDING (WCP)	Cracked	116.00 F	*116.00 F
26	1		*FRONT GRILLE SUPPORT (WCP)	Cracked	178.00 F	*178.00 F
27	1		*FRONT GRILLE INNER GARNISH (WCP)	Cracked	95.00 F	*95.00 F
28	1		*FRONT BUMPER (WCP)	Cracked	850.00 F	*850.00 F
29	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	395.00 F	*395.00 F
30	1		*FRONT BUMPER BRACKET - LH (WCP)	Not Necessary	168.00 F	*- F
31	1		*FRONT BUMPER INNER CARRIER - LH (WCP)	Cracked	75.00 F	*75.00 F
32	1		*FRONT BUMPER STRUT - LH (WCP)	Bent	42.00 F	*42.00 F
33	1		*FRONT BUMPER SPONGE (WCP)	Cracked	152.00 F	*152.00 F
34	1		*FRONT BUMPER CENTRE GRILLE (WCP)	Dented	96.00 F	*96.00 F
35	1		*FRONT BUMPER LOWER INNER FRAME (WCP)	Cracked	105.00 F	*105.00 F
36	1		*FRONT BUMPER SIDE RETAINER - LH (WCP)	Distorted	24.00 F	*24.00 F
37	1		*FRONT BUMPER SENSOR (WCP)	Dented	138.00 F	*138.00 F
38	6		*FRONT BUMPER SENSOR SEAL (WCP)	Necessary	48.00 F	*48.00 F
39	1		*FRONT BUMPER SENSOR CABLE (WCP)	Not Necessary	130.00 F	*- F
40	1		*FRONT BUMPER LOWER CHROME (WCP)	Cracked	118.00 F	*118.00 F
41	1		*FRONT BUMPER LOWER LID (WCP)	Cracked	115.00 F	*115.00 F
42	1		*FRONT BUMPER UNDER COVER (WCP)	Cracked	168.00 F	*168.00 F
43	1		*FRONT NUMBER PLATE GARNISH (WCP)	Not Necessary	98.00 F	*- F
44	1		*FRONT FENDER - LH (WCP)	Repair	628.00 F	*- F
45	20		*FRONT FENDER INNER SHIELD CLIPS - LH (WCP)	Not Necessary	130.00 F	*- F
46	1		*FRONT SPORT RIM - LH (WCP)	Dented	750.00 F	*750.00 F
47	1		*ERP BRACKET	Necessary	35.00 FS	*26.00 FS
48	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
49	1		*FRONT NUMBER PLATE	Missing	40.00 FS	*40.00 FS
50	1		*KNEE AIRBAG UNDER COVER (WCP) (Supplementary)	Cracked	250.90 F	*250.90 F
51	1		*FRONT BUMPER UNDER COVER - LH (WCP) (Supplementary)	Cracked	88.00 F	*88.00 F
52	1		*FRONT BUMPER PRESSURE SENSOR (WCP) (Supplementary)	Distorted	155.00 F	*155.00 F
53	2		*HORN BRACKET - RH / LH (WCP) (Supplementary)	Bent	56.00 F	*56.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	10		*BONNET INSULATOR CLIPS	Necessary	71.50 FS	*40.00 FS
55	1		*SUPPORT PANEL TOP GARNISH CLIPS (6PCS)	Necessary	33.00 FS	*20.00 FS
56	1		*FRONT BUMPER CLIPS (15PCS)	Necessary	90.75 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	26,510.15	24,638.90
+ Margin on L,N Items 10.00/10.00% (\$\$)	2,617.99	2,442.29
Total Parts (\$\$)	29,128.14	27,081.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT AIR-CON CONDENSER AND REFILL AIR-CON GAS	New	150.00	0.00
2	TO REMOVE AND REFIT DASHBOARD, METER AND GROVE BOX COMPARTMENT TO FACILITATES THE REPAIR	New	580.00	300.00
3	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	150.00	120.00
4	TO DISMANTLE AND REFIT CONSOLE BOX TO ENABLE REPLACE AIRBAG CONTROL UNIT	New	280.00	180.00
5	TO REMOVE AND REPLACE ROOFING LINING	New	120.00	80.00
6	TO REMOVE AND REPLACE STEERING AIRBAG, PASSENGER AIRBAG, KNEE AIRBAG, FRONT AND REAR SAFETY BELT, AIRBAG CONTROL UNIT AND AIRBAG SENSOR	New	800.00	400.00
7	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
8	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER INNER PANEL, LH FRONT CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,500.00	600.00
9	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	600.00
10	TO RE-PROGRAM AND RESET ALL CONTROL MODULE FAULTY CODE	New	580.00	480.00
			Gross Labour Cost (S\$)	5,440.00
				2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >