

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21008679/R1QF3N2**Date:** 23/08/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210068631
Claimant Vehicle No :	FBN4026C	Insured Vehicle No :	SMM6723K
Date of Loss:	30/07/2021	Nature of Claim:	TP
		Claim No:	9030398417SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN4026C	Engine No:	KB21E1069857
Make & Model:	HONDA SUPRA GTR 150, 149cc	Chassis No:	MH1KB2110JK069762
Reg. Date:	21/09/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/80-17	Rear Tyre Size:	120/70-17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/08/2021	Hua Chin (2000) Trading Motor Service Centre (HQ)
Date Inspected:	19/08/2021 Inspected At:	50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING
Estimated Period of Repair:	4.0 days	Singapore 659578

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$8,800.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Cut	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
3	1		*FRONT FORK ASSY	Cut	0.00 F	*- F
4	1		*FRONT WING MIRROR	Cracked	0.00 F	*- F
5	1		*ERP UNIT	Scratched	0.00 F	*- F
6	1		*CLUTCH LEVER	Bent	0.00 F	*- F
7	1		*SIDE FAIRING	Scratched	0.00 F	*- F
8	1		*SIDE FAIRING INNER GARNISH	Scratched	0.00 F	*- F
9	1		*CENTER FAIRING GARNISH	Scratched	0.00 F	*- F
10	1		*HANDPHONE HOLDER	Scratched	0.00 F	*- F
11	1		*FOOT BRAKE	Bent	0.00 F	*- F
12	1		*CLUTCH ENGINE COVER	Scratched	0.00 F	*- F
13	1		*EXHAUST MUFFLER ASSY COVER	Scratched	0.00 F	*- F
14	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
15	1		*REAR BOX	Scratched	0.00 F	*- F
					F=Franchise part.	
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >