

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008681/DQCN2**Date:** 27/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004192100

Claimant Vehicle No : GV7577H **Insured Vehicle No :** SLC337X

Date of Loss: 11/08/2021 Nature of Claim: TP Claim No: SNM21D204517/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GV7577H**

Make & Model: MERCEDES-BENZ VITO 111, 2.1 D L (M) Engine No: 64698051319442

Reg. Date: 01/06/2007 (Man. Year: 2007) Chassis No: WDF63960323316637

Colour: Silver Odometer: 376551 km

Engine Capacity: 2148 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,580.00	271.80	4,308.20	94.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,000.00	1,260.00	55.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,840.00	1,271.80	5,568.20	81.41
Approved Total (Overridden) (\$\$)		1,000.00		
Nett Amount (\$\$)	6,840.00	1,000.00	5,840.00	85.38

INSPECTION

Date of Assignment: 18/08/2021

Date Inspected: 19/08/2021 Inspected At: Alfred Auto Services & Supplies (HQ)
Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2
Singapore 569538

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Oct 2021)	
Parts:	N/A	MERCEDES-BENZ VITO 111 2.1 D L (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GV7577H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Repair	1,490.00 F	*- FN
2	1		*RH FRONT DOOR PROCTER	Necessary	310.00 F	*135.50 FN
3	1		*RH CENTRE SIDE DOOR	Repair	1,880.00 F	*- FN
4	1		*RH CENTRE SIDE DOOR PROCTER	Necessary	330.00 F	*166.50 FN
5	1		*RH CENTRE SIDE DOOR GLASS MOULDING	Serviceable	380.00 F	*- FN
6	1		*SET GLASS SELANT & REPAIR KIT	Not Necessary	190.00 F	*- FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	4,580.00	302.00
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	30.20
Total Parts (\$\$)	4,580.00	271.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT SIDE DOOR GLASS	New	180.00	0.00
2	TO CHECK WIRING & REMOVE & REFIT SIDE DOOR & FRONT DOOR WIRING	New	280.00	0.00
3	TO REPAIR & RENEW ON ALL ACCIDENT AFFECTED AREA	New	800.00	500.00
4	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA	New	1,000.00	500.00
Gross Labour Cost (\$\$)			2,260.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >