

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21008684/RES3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993734
<b>Claimant Vehicle No :</b>	SLG3253M	<b>Insured Vehicle No :</b>	SKF5486L
Date of Loss:	16/08/2021	Nature of Claim:	TP
		Claim No:	4407939501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLG3253M</b>	Engine No:	2ZR1827011
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W00J004943
Reg. Date:	28/09/2016 (Man. Year: 2016)	Odometer:	127214 km
Colour:	Purple		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,190.17	3,705.17	11,485.00	75.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,110.00	1,590.00	3,520.00	68.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,300.17</b>	<b>5,295.17</b>	<b>15,005.00</b>	<b>73.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>(S\$)</b>	20,300.17	4,200.00	16,100.17	79.31
<b>+ GST 7.00/7.00% (S\$)</b>	1,421.01	294.00	1,127.01	79.31
<b>Nett Amount (S\$)</b>	<b>21,721.18</b>	<b>4,494.00</b>	<b>17,227.18</b>	<b>79.31</b>
<b>+ Loss of Use (9.0 x S\$80.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>5,221.49</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,220.00</b>		

INSPECTION

Date of Assignment:	18/08/2021	My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Date Inspected:	19/08/2021 Inspected At:	
Estimated Period of Repair:	7.0 days	

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	698.00 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	68.00 FL	*- FL
3	1		*HEADLAMP RH	Serviceable	859.60 FL	*- FL
4	1		*FRONT FENDER RH	Bent	898.60 FL	*689.00 FL
5	1		*FRONT FENDER COWLING RH	Deformed	196.60 FL	*150.00 FL
6	1		*FRONT QUARTER GLASS WITH MOULDING RH	Serviceable	656.00 FL	*- FL
7	1		*FRONT DOOR VIEW MIRROR RH	Serviceable	989.60 FL	*- FL
8	1		*FRONT DOOR RH	Torn	1,277.90 FL	*1,277.90 FL
9	1		*FRONT DOOR STEP GARNISH RH	Serviceable	155.00 FL	*- FL
10	1		*FRONT DOOR STEP GARNISH INNER RH	Serviceable	245.00 FL	*- FL
11	1		*FRONT DOOR INNER LOCK RH	Bent	589.00 FL	*420.00 FL
12	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	215.00 FL	*155.00 FL
13	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	589.00 FL	*- FL
14	1		*FRONT DOOR REGULATOR RH	Bent	458.00 FL	*159.00 FL
15	1		*FRONT DOOR INNER TRIM BOARD RH	Cracked	598.00 FL	*598.00 FL
16	1		*FRONT DOOR OUTER MOULDING RH	Serviceable	142.60 FL	*- FL
17	1		*FRONT DOOR OUTER HANDLR RH	Serviceable	212.00 FL	*- FL
18	1		*FRONT DOOR PILLAR RH	Repair	865.00 FL	*- FL
19	2		*FRONT DOOR HINGE RH	Serviceable	250.00 FL	*- FL
20	1		*FRONT DOOR CHROME MOULDING PROTECTOR RH	Cracked	259.00 FL	*259.00 FL
21	1		*ROCKER PANEL RH	Repair	789.20 FL	*- FL
22	1		*CENTRT PILLER RH	Repair	854.00 FL	*- FL
23	1		*ABS SENSOR RH	Serviceable	357.60 FL	*- FL
24	1		*FRONT KNUCKLE ARM RH	Serviceable	489.70 FL	*- FL
25	1		*FRONT KNUCKLE BEARING RH	Serviceable	235.90 FL	*- FL
26	1		*FRONT WHEEL HUP RH	Serviceable	494.20 FL	*- FL
27	1		*FRONT SHOCK ABSORBER RH	Serviceable	488.90 FL	*- FL
28	1		*FRONT LOWER ARM RH	Serviceable	561.60 FL	*- FL
29	1		*REAR DOOR RH	Repair	1,277.90 FL	*- FL
30	1		*REAR DOOR INNER TRIM BOARD RH	Serviceable	412.00 FL	*- FL
31	1		*REAR DOOR BLACK STICKER RH	Serviceable	129.00 FL	*- FL
32	1		*REAR DOOR CHROME MOULDI NG PROTECTOR RH	Scratched	259.00 FL	*259.00 FL
33	1		*SET FRONT BUMPER CLIP	Not Necessary	60.00 FS	*- FS
34	1		*SET FRONT FENDER COWLING CLIP	Necessary	50.00 FS	*30.00 FS
35	1		*FRONT QUARTER GLASS INNER SEAL RH	Not Necessary	60.00 FS	*- FS
36	1		*FRONT QUARTER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
37	1		*SET FRONT DOOR TRIM BOARD CLIP	Necessary	60.00 FS	*20.00 FS
38	1		*FRONT DOOR SEALANT RH	Not Necessary	80.00 FS	*- FS
39	1		*SET FRONT DOOR INNER TRIM CLIPS	Not Necessary	32.00 FS	*- FS
40	1		*FRONT WHEEL TYRE RH	Not Necessary	320.00 FS	*- FS
41	1		*FRONT WHEEL RIM RH	Not Necessary	650.00 FS	*- FS
42	1		*CENTER PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*SET CENTER PILLAR INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
44	1		*SIDE SKIRT RH	Scratched	1,200.00 FS	*680.00 FS
45	1		*SET REAR DOOR INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>19,332.90</b>	<b>4,696.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	4,142.73	991.73
<b>Total Parts (\$)</b>	<b>15,190.17</b>	<b>3,705.17</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT ,WELD ,CUT ,ADJUST ,KNOCK	New	1,400.00	700.00
2	TO SPRAY PAINT	New	1,400.00	800.00
3	TUFF COAT	New	200.00	30.00
4	WIRING ,BULB CHECKING	New	180.00	0.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	400.00	0.00
6	REMOVE & REFIX REAR UNDERCARRIAGE	New	550.00	0.00
7	TRANFER FRONT DOOR MECHANISM	New	120.00	60.00
8	TRANFER REAR DOOR MECHANISM	New	120.00	0.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	500.00	0.00
10	REMOVE AND REFIT REAR QUARTER GLASS	New	120.00	0.00
11	FOUR WHEEL ALIGNMENT	New	120.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>5,110.00</b>
				<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >