10/29/21, 2:28 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21008685/KEA3Q2

Date:

29/10/2021

REFERENCE

Date of Loss:

Reg. Date:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800123738 SLG9075X

Claimant Vehicle No :

SLJ3821H 14/08/2021 Insured Vehicle No:
Nature of Claim:

TP

Claim No:

5637330424SG

JN1TBAE12Z0982548

HR12186434B

216604 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ3821H

Make & Model: NISSAN NOTE, 1.2 DIG-S CVT (A)

08/12/2016 (Man. Year: 2016)

Toyo 8 mm

Colour: Metallic Blue Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Service

Steering (Serviceable):

Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Right Side:

Front Tyre Size: 185/65 R15
Front Left Side: Toyo 8 mm

Rear Tyre Size: 185/65 R15 Rear Left Side: Yokohama 8 mm

Rear Right Side:

Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,951.79	3,625.02	1,326.77	26.79
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,220.00	1,630.00	590.00	26.58
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,171.79	5,255.02	1,916.77	26.73
	Approved Total (Overridden) (S\$)		4,100.00		

Nett Amount (S\$) 7,171.79 4,100.00 3.071.79 42.83 + Car Rental (5.0 x S\$100.00/day) (S\$) 500.00 **Nett Liability (S\$)** 4,600.00

INSPECTION

Date of Assignment: 18/08/2021

Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10 Date Inspected: 18/08/2021 Inspected At:

Singapore 575645

Estimated Period of Repair: 6.0 days

KENNETH KONG Adjuster: Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
l 1	*REAR TAILGATE	Bent	1,018.20 FN	*976.40 FN
2 1	*REAR TAILGATE RUBBER (50%)	Cut	61.38 FS	*34.10 FS
3 1	*REAR TAILGATE LOCK UPPER	Dented	128.40 FN	*128.40 FN
1 1	*REAR EMBLEM LOGO	Necessary	64.90 FN	*64.90 FN
5 1	*REAR EMBLEM NOTE	Necessary	79.90 FN	*79.90 FN
3 1	*REAR EMBLEM DIG-S	Necessary	56.20 FN	*56.20 FN
7 1	*REAR TAILGATE OUTER HANDLE	Warped	281.10 FN	*281.10 FN
3 1	*REAR WIPER MOTOR	Serviceable	296.30 FN	*- FN
9 1	*REAR WIPER ARM	Serviceable	115.90 FN	*- FN
10 2	*REAR TAILLAMPS	Cut	871.60 FN	*646.20 FN
11 1	*REAR BUMPER	Buckled	460.00 FN	*434.00 FN
12 2	*REAR BUMPER RETAINER	Distorted	70.40 FN	*70.40 FN
13 1	*REAR BUMPER SPONGE	Serviceable	137.80 FN	*- FN
14 1	*REAR END PANEL	Bent	552.80 FN	*552.30 FN
l5 1	*REAR END PANEL TOP GARNISH	Distorted	85.00 FN	*85.00 FN
16 1	*REAR FENDER INNER GARNISH/RH	Serviceable	396.40 FN	*- FN
17 1	*REAR NO PLATE }	Dented	25.00 FS	*25.00 FS
18 1	*REAR NO PLATE HOLDER }		25.00 FS	*-FS
19 1	*SET REAR REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
20 2	*REAR TAILEND PANEL TEROSTAT SEALANT	Necessary	108.40 FS	*30.00 FS
21 1	*REAR W/SCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
22 1	*REAR W/SCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
23 1	*REAR W/SCREEN MLDG	Necessary	159.00 FN	*159.00 FN
24 5	*REAR BUMPER FASTENER	Necessary	40.00 FN	*40.00 FN
25 5	*REAR BUMPER EXTENSION FASTENER	Necessary	27.50 FN	*27.50 FN
26 5	*REAR BUMPER EXTENSION GROMMET SCREW	Necessary	27.50 FN	*27.50 FN
=Franchise part. S=SpcNett.	N=NettItemDisc.			
		Sub Total (S\$)	5,438.68	3,987.90
		- Nett Item Discount on N Items 10.00/10.00% (S\$)	486.89	362.88
		Total Parts (S\$)	4,951.79	3,625.02
	Report was III	nsubmitted during this print-out.		

10/29/21, 2:28 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	60.00
2	TO CHECK WATER SEEPAGE	New	60.00	20.00
3	TO REMOVE & REFIX REAR W/SCREEN GLASS	New	150.00	120.00
4	TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS	New	60.00	50.00
5	TO REPAIR ,PANEL BEAT ,ALIGN ON REAR AFFECTED AREA ,CUT & WELD ON REAR PANEL & LABOUR TO REPLACE THE ABOVE PART	New	800.00	600.00
6	TO PUTTY ,PRIMER & SPRAY PAINT ON REAR TAILGATE,REAR END PANEL,REAR BUMPER & REAR REVERSE SENSOR	New	800.00	660.00
7	TO TRANSFER TAILGATE PARTS & FITTING TO NEW TAILGATE	New	80.00	60.00
8	LABOUR TO REMOVE/REFIX REAR SEAT ,INTERIOR GARNISH ETC IN ORDER TO FACILITATE REPAIR JOB	New	150.00	60.00
	Gross Labour Cost (S\$		2,220.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >