



Inspection Services Pte Ltd

VEHICLE DAMAGE INSPECTION REPORT

Our File No: AVS2019-21017/BL
Date: 14/10/2019

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC19A00094603
Claimant Vehicle No : SJU3505L **Insured Vehicle No :** SJE4623G
Date of Loss: 08/06/2019 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU3505L**
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 3ZRA414677
Reg. Date: 30/11/2009 (Man. Year: 2009) Chassis No: JTDGJ20W405001456
Colour: Silver Odometer: 102782 km
Engine Capacity: 1987 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50R17 Rear Tyre Size: 215/50R17
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/10/2019
Date Inspected: 10/10/2019 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
Singapore 417921
Estimated Period of Repair: 0.0 days

Adjuster: Billy Loh Surveyor
Manager: Bernard Ong Director

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



AJAX Inspection Services Pte Ltd

2 Alexandra Road, #03-01B Delta House, Singapore 159919. Tel: +65 6271 2520 Fax: +65 6271 2526
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

MARKET VALUE

The present market value of the subject vehicle is in the region of S\$12,500.00.

REMARKS

Third Party Repairer did not provide any repair estimate to us and is only requesting for us to conduct a PRE-REPAIR INSPECTION.

Based on visual inspection of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than S\$3,000.00 and could take approximately four (4) working days to complete. However, please kindly take note that the economical repair value (ERV) is about S\$1,250.00.

All the stated damage are subject to consistency of the mentioned accident.

The survey was conducted strictly on a "Without Prejudice" basis.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Oct 2019)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **AJAX Inspection Services Pte Ltd/SJU3505L/14/10/2019 17:15**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

AJAX Inspection Services Pte Ltd/SJU3505L/14/10/2019 17:15. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

AJAX Inspection Services Pte Ltd/SJU3505L/14/10/2019 17:15. Not valid without Reference section.

< END OF ESTIMATES >