

ASS. BY:

REF: OS/LAW 21008686/Duf 3

ASSIGNMENT

COE NOV 2019

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 CD / FWS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SJU 3505L  
 at Worktop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured SJE 4623G  
 Policy Et T140.111787.19  
 Claimer b. CMTD2001923  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Check Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SJU 3505L Yr Regn: Nov, 2009  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Wish C.C. 1794  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading 132679 T/Radio: Insured / Std / NI / NA  
 Eng/No: 3ZRA414677  
 C/No: JTDGJ20W405001456  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 215/50 R17  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Zwenza  
 Front S mm R/Bal. S mm  
 Rear S mm R/Bal. S mm  
 L/Bal. S mm L/Bal. S mm  
 D.O.A. 08/10/2019 D.O.L. 17/09/2021  
 Survey held at Twin Car Kaki Bukit.  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Police Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: \_\_\_\_\_  
 IDAC Accident Report Consistent?: Yes or No  
 GIA / PR Seen: Consistent?: Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Turn Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>SOE physical re-inspection - 30/09/2021 - To submit HS 2750 with 4 days: (RED \$4750, 63%)</u>
	<u>Vehicle COE lifespan at time of accident is about to slightly more than 1 mth left. However vehicle has since renewed COE till 2029.</u>
	<u>Shop informed vehicle met with accident again after this accident.</u>
	<u>MV at time of loss 12.5K } Physical re-inspection no</u>
	<u>LTA — " — 11.2k } To indicate in use. Assessment based</u>
	<u>NL — " — 1.3K } remark column. on paper survey.</u>

Date/Time, File Pass to?  : Prel. Report Days Of Repair: 4  
 1) 30/9 TYPIST  : Final Report Resurvey No. of Trip: \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$) ) S + RS. SI  
 : Interview (\$) ) Photos  
 : Tech. Invs (\$) ) Others

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 594J

### Vehicle Details

Vehicle No.: SJU3505L  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 10 Sep 2021  
Vehicle Make: TOYOTA  
Vehicle Model: WISH 2.0 AUTO  
Primary Colour: Silver  
Manufacturing Year: 2009  
Engine No.: 3ZRA414677  
Chassis No.: JTDGJ20W405001456  
Maximum Power Output: 106.0 kW (142 bhp)  
Open Market Value: \$22,003.00  
Original Registration Date: 30 Nov 2009  
First Registration Date: 30 Nov 2009  
Transfer Count: 1  
Actual ARF Paid: \$22,003.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Oct 2029  
COE Category: E - Open Category  
COE Period(Years): 10  
PQP Paid: \$37,502.00  
COE Rebate Amount: \$30,525.00  
**Total Rebate Amount: \$30,525.00**

The information contained herein is correct as at 10 Sep 2021

OK

## PARTS

### Parts and Labour Assessment

Description of part	Qty	Condition	Repairer's estimate	Our adjustment	
REAR BUMPER	1	squashed	698.10	698.10	✓
REAR BUMPER REFLECTOR L/R	2	reuse	190.00	0.00	HH
REAR BUMPER SIDE RETAINER L/R	2	necessary	282.90	282.90	HH
REAR END LOWER PANEL	1	buckled	463.20	463.20	✓
REAR END PANEL	1	buckled	591.40	591.40	✓
REAR END PANEL INNER TOP GARNISH	1	fractured	289.90	289.90	✓
REAR EXHAUST GASKET	1	necessary	61.75	61.75	HH
REAR EXHAUST RUBBER MOUNTING	2	distorted	123.40	123.40	HH
REAR EXHAUST SILENCER BOX	1	bent	971.00	971.00	HH
REAR FLOOR PANEL TOP BOARD COVER	1	reuse	498.70	0.00	HH
REAR SPARE TYRE CARRIAGE	1	jammed/bent	328.70	328.70	HH
REAR TAILGATE	1	buckled	1,515.00	1,515.00	R
REAR TAILGATE 'LOGO' EMBLEM	1	necessary	72.50	72.50	✓
REAR TAILGATE DAMPER L/R	2	reuse	598.20	0.00	HH
REAR TAILGATE HINGES L/R	2	repair	363.00	0.00	HH
REAR TAILGATE INNER PULL HANDLE	1	reuse	131.20	0.00	HH
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	2	deformed	87.40	87.40	HH
REAR TAILGATE INNER TRIM BOARD	1	reuse	708.85	0.00	HH
REAR TAILGATE LOCK STRIKER	1	repair	48.30	0.00	HH
REAR TAILGATE MECHANISM LOCK	1	bent	517.10	517.10	HH
REAR TAILGATE NUMBER PLATE LAMP L/R	2	reuse	166.50	0.00	HH
REAR TAILGATE OUTER CHROME HANDLE	1	reuse	313.90	0.00	HH
REAR TAILGATE REFLECTOR L/R	2	reuse	616.60	0.00	HH
REAR TAILGATE WEATHER STRIP	1	deformed	320.00	320.00	✓
REAR TAILGATE WINDSCREEN MOULDING (LOWER)	1	necessary	68.00	68.00	HH
REAR TAILGATE WINDSCREEN MOULDING (TOP)	1	necessary	68.00	68.00	HH
REAR TAILGATE WINDSCREEN MOULDING L/R	2	necessary	220.70	220.70	HH
Subtotal before discount			S\$ 10,314.30	S\$ 6,679.05	
Percentage discount 25% and 25%			S\$ 2,578.58	S\$ 1,669.76	
<b>Sub-total 1</b>			<b>S\$ 7,735.73</b>	<b>S\$ 5,009.29</b>	
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	<del>350.00</del>	220/-
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	50.00	<del>50.00</del>	15/-
REAR FLOOR PANEL INSULATOR MAT	1	necessary	300.00	300.00	HH
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	necessary	50.00	50.00	HH
REAR TAILGATE NUMBER PLATE	1	reuse	25.00	0.00	HH
REAR TAILGATE NUMBER PLATE HOLDER	1	reuse	50.00	0.00	HH
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET	1	necessary	50.00	50.00	HH
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00	HH
Subtotal before discount			S\$ 975.00	S\$ 900.00	
<b>Sub-total 2</b>			<b>S\$ 975.00</b>	<b>S\$ 900.00</b>	
<b>Parts-total</b>			<b>S\$ 8,710.73</b>	<b>S\$ 5,909.29</b>	

235.00 //

## LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	100.00	60.00	30/-
To remove, reinstall tailgate windscreen	300.00	150.00	NH
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00	✓
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	1,100.00	600/-
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	180.00	120.00	60/-
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,500.00	1,250.00	600/-
To apply anti-rust chemical on repaired and replaced panel.	120.00	60.00	40/-
To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.	100.00	60.00	NH
	<b>Labour Total</b>	<b>S\$ 3,640.00</b>	<b>S\$ 2,860.00</b>
	<b>Parts &amp; Labour Total</b>	<b>S\$ 12,350.73</b>	<b>S\$ 8,769.29</b>

1390.00 =

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 7,500.00  
and the recommended number of working days for the repairs is within 8 day(s).

  
B J Loi (I Eng., MIMI, AIRTE)  
Automotive Appraiser

34511.312  
4/5 2750/-

4 days