

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21008687/KTF3N2**Date:** 26/08/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006849
Claimant Vehicle No :	SLS483Y	Insured Vehicle No :	SMA7822P
Date of Loss:	13/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003503

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS483Y	Engine No:	1AZH332071
Make & Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Chassis No:	JTEGH23B300026524
Reg. Date:	15/05/2009 (Man. Year: 2009)	Odometer:	159367 km
Colour:	Metallic Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,442.68	3,956.71	5,485.97	58.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	2,260.00	1,240.00	35.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,942.68	6,216.71	6,725.97	51.97
Approved Total (Overridden) (S\$)		4,950.00		
Nett Amount (S\$)	12,942.68	4,950.00	7,992.68	61.75

INSPECTION

Date of Assignment:	19/08/2021		160 SIN MING DRIVE #03-18/19
Date Inspected:	17/08/2021	Inspected At:	SIN MING AUTOCITY
			SINGAPORE 575722
			REPAIRER: EM SOLUTION PTE LTD
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Aug 2021)

Parts: M1-MPV TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS483Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,460.50 FL	*1,307.00 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	181.95 FL	*181.95 FL
3	1		*TAILGATE LOGO	Necessary	68.60 FL	*68.60 FL
4	1		*TAILGATE EMBLEM TOYOTA	Necessary	81.50 FL	*81.50 FL
5	1		*TAILGATE EMBLEM PICNIC	Necessary	81.50 FL	*81.50 FL
6	2		*TAILGATE LAMPS-L/R	Serviceable	763.10 FL	*- FL
7	1		*TAILGATE OUTER MOULDING	Serviceable	191.35 FL	*- FL
8	1		*TAILGATE INNER LOCK	Repair	411.53 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Serviceable	410.95 FL	*- FL
10	2		*TAILGATE STOPPERS	Serviceable	21.00 FL	*- FL
11	1		*TAILLAMP-RH	Serviceable	863.00 FL	*- FL
12	1		*REAR BUMPER	Buckled	610.50 FL	*586.20 FL
13	1		*REAR BUMPER TOW COVERS-L/R	O/s Dented	83.10 FL	*41.55 FL
14	2		*REAR BUMPER REFLECTORS-L/R	Serviceable	220.50 FL	*- FL
15	2		*REAR BUMPER SIDE BRACKETS-L/R	Serviceable	128.86 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINERS-L/R	Serviceable	173.10 FL	*- FL
17	1		*REAR END PANEL	Bent	681.90 FL	*681.90 FL
18	1		*REAR END PANEL TRIM	Dented	241.60 FL	*241.60 FL
19	1		*REAR EXHAUST SILENCER	Repair	760.90 FL	*- FL
20	1		*REAR FLOOR BOARD	Serviceable	781.60 FL	*- FL
21	1		*REAR FLOOR MAT	Cracked	531.60 FL	*531.60 FL
22	1		*TAILGATE W/STRIP (50%)	Dented/Distorted	195.70 FS	*130.46 FS
23	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
25	1		*SET REAR REVERSE SENSOR	Dented	350.00 FS	*300.00 FS
26	1		*REAR REVERSE CAMERA	Serviceable	450.00 FS	*- FS
27	1		*REAR FLOOR PANEL	Bent	791.60 FL	*791.60 FL
28	2		*REAR FENDER INNER TRIM BOARDS-L/R	Serviceable	1,562.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,218.34	5,105.46
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,775.66	1,148.75
Total Parts (\$\$)	9,442.68	3,956.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
3	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	80.00
4	TO REMOVE,REFIX REAR CAMERA/REVERSE SENSOR	New	80.00	60.00
5	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	120.00	0.00
6	TO RESPRAY UNDERCOATING	New	120.00	80.00
7	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
8	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,600.00	1,100.00
Gross Labour Cost (\$\$)			3,500.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >