

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21008692/EPS3Q2
Date: 18/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMF2986G	Insured Vehicle No :	SBW999Z
Date of Loss:	18/08/2021	Nature of Claim:	TP
		Claim No:	9634417037SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF2986G	Engine No:	CZD179452
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)	Chassis No:	WVGZZZ1TZKW006366
Reg. Date:	31/10/2018 (Man. Year: 2018)	Odometer:	70505 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,143.23	5,511.11	3,632.12	39.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,630.00	5,170.00	6,460.00	55.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,773.23	10,681.11	10,092.12	48.58
+ GST 7.00/7.00% (S\$)	1,454.13	747.68	706.45	48.58

Nett Amount (S\$)	22,227.36	11,428.79	10,798.57	48.58
+ Car Rental (7.0 x S\$80.00/day + 7.00% GST) (S\$)		599.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,029.99		

INSPECTION

Date of Assignment: 20/08/2021

Date Inspected: 20/08/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Dented	2,382.62 FS	*2,382.62 FS
2	2		*1K WINDOW ADHESIVE	Necessary	102.32 FS	*102.32 FS
3	1		*ALL PURPOSE CLEANER	Necessary	97.37 FS	*97.37 FS
4	1		*PRIMER	Necessary	28.44 FS	*28.44 FS
5	1		*ACTIVATOR FOR PRECOATED W	Necessary	26.15 FS	*26.15 FS
6	2		*APPLICATOR	Necessary	20.88 FS	*20.88 FS
7	1		*SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM LH	Necessary	266.78 FS	*266.78 FS
8	1		*SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM RH	Necessary	279.12 FS	*279.12 FS
9	1		*PACKING ADHESIVE RR NUMBER PLATE PACKING	Cut	30.50 FS	*30.50 FS
10	2		*RIVETTED CAP NUT	Necessary	5.00 FS	*5.00 FS
11	1		*HOOD LATCH LID LOCK	Not Necessary	174.72 FS	*- FS
12	1		*COVER LOCK SATIN BLACK	Not Necessary	20.44 FS	*- FS
13	1		*PUSHBUTTON FOR ELECTRIC L	Not Necessary	1,505.90 FS	*- FS
14	1		*GASKET LID WETHERSTRIP	Not Necessary	324.94 FS	*- FS
15	1		*VW SIGN BLACK/BRIGHT CHRO	Necessary	108.20 FS	*108.20 FS
16	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -TOURAN	Necessary	74.19 FS	*74.19 FS
17	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKELIGHT	Not Necessary	228.77 FS	*- FS
18	2		*LED LICENCE PLACE LIGHT	Not Necessary	207.94 FS	*- FS
19	1		*COVER FOR BUMPER PRIMED	Dented	1,438.75 FS	*1,438.75 FS
20	1		*SPOILER SATIN BLACK	Cut	331.24 FS	*331.24 FS
21	1		*BUMPER REINFORCEMENT	Not Necessary	549.77 FS	*- FS
22	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	65.34 FS	*- FS
23	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	42.45 FS	*- FS
24	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	42.45 FS	*- FS
25	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	34.70 FS	*- FS
26	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	34.70 FS	*- FS
27	4		*RIVET	Necessary	4.72 FS	*4.72 FS
28	6		*WELD STUD	Necessary	6.06 FS	*6.06 FS
29	1		*REAR NUMBER PLATE	Necessary	80.00 FS	*80.00 FS
30	1		*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
31	1		*BRAKE LIGHT WI	Necessary	228.77 FS	*228.77 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)**9,143.23****5,511.11**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	4,200.00	1,680.00
4	SPRAY PAINT	New	4,000.00	1,600.00
5	R&R REAR W/SCREEN	New	840.00	840.00
6	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
7	REAR WATER LEAK TEST	New	150.00	150.00
8	R&R REAR LUGAGE TRIM TO REPAIR END PANEL	New	840.00	0.00
			Gross Labour Cost (S\$)	11,630.00
				5,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >