

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008696/KRS3Q2
Date: 11/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700017530
Claimant Vehicle No :	SMH6724J	Insured Vehicle No :	SLP7782D
Date of Loss:	18/08/2021	Nature of Claim:	TP
		Claim No:	3916633603SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH6724J		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	LEB5926876
Reg. Date:	29/01/2019 (Man. Year: 2016)	Chassis No:	RU31226864
Colour:	Metallic Grey	Odometer:	169458 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,212.24	2,480.88	2,731.36	52.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,375.00	1,175.00	46.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,762.24	3,855.88	3,906.36	50.33
Approved Total (Overridden) (S\$)		3,050.00		

(S\$)	7,762.24	3,050.00	4,712.24	60.71
+ GST 7.00/7.00% (S\$)	543.36	213.50	329.86	60.71
Nett Amount (S\$)	8,305.60	3,263.50	5,042.10	60.71
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,765.50		

INSPECTION

Date of Assignment: 19/08/2021

Date Inspected: 19/08/2021

Estimated Period of Repair: 5.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	972.40 FL	*953.00 FL
2	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.60 FL	*75.60 FL
3	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	65.60 FL	*65.60 FL
4	1		*REAR TAILGATE INNER LOCK	Dented	116.40 FL	*116.40 FL
5	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	203.50 FL	*- FL
6	1		*REAR TAILGATE WEATHERSTRIPE	Serviceable	138.60 FL	*- FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	105.20 FL	*105.20 FL
8	1		*REAR TAIL LAMP LH	Serviceable	486.70 FL	*- FL
9	1		*REAR TAIL LAMP RH	Serviceable	486.70 FL	*- FL
10	1		*REAR BUMPER	Buckled	829.60 FL	*762.70 FL
11	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	37.50 FL	*- FL
12	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	37.50 FL	*- FL
13	1		*REAR BUMPER REFLECTOR LH	Serviceable	108.50 FL	*- FL
14	1		*REAR BUMPER REFLECTOR RH	Serviceable	108.50 FL	*- FL
15	1		*REAR BUMPER SMART BUZZER	Cracked	110.10 FL	*110.10 FL
16	1		*REAR SIDE BUMPER LH	Serviceable	148.50 FL	*- FL
17	1		*REAR SIDE BUMPER RH	Serviceable	148.50 FL	*- FL
18	1		*REAR END PANEL	Repair	452.40 FL	*- FL
19	1		*REAR SPARE TYRE TRAY	Serviceable	236.10 FL	*- FL
20	1		*REAR SPARE TYRE TRAY UPPER BOARD	Serviceable	459.90 FL	*- FL
21	1		*REAR TAILGATE INNER TRIM CLIPS	Necessary	40.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
23	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
25	1		*REAR END PANEL JOINT SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*REAR END PANEL UPPER COVER (CHROME)	Dented	180.00 FS	*180.00 FS
27	1		*REAR BUMPER CHROME MOULDING	Dented	220.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,277.80	2,918.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,065.56	437.72
Total Parts (\$)	5,212.24	2,480.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO RMEOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	1,000.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR SIDE BUMPER LH ,REAR SIDE BUMPER RH,REAR END PANEL & ETC	New	1,000.00	600.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING REAR WINDSCREEN SEALANT & ETC .TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR &ETC	New	100.00	50.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	30.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	15.00
Gross Labour Cost (S\$)			2,550.00	1,375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >