



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 5584T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FENDER RHR DJ/DL (SN)	TO REPAIR SEE LABOUR	886.20	-
1	GUARD (R),STONE-FRT DJ (SN)	NECESSARY	14.70	14.70
1	BODY (R),DOOR MIRROR DJ/DL (SN)	NOT NECESSARY	372.80	-
1	GLASS & HOLDER (R),MI (SN)	NOT NECESSARY	49.50	-
1	LAMP (R),SIDE TURN DL (SN)	NOT NECESSARY	56.60	-
1	HOUSING (R),DR MIRROR (SN)	NOT NECESSARY	81.20	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			1,511.00	34.70
	<b><u>LABOUR</u></b>			
	TO REPLACE REAR FENDER RH.TO REPAIR REAR DOOR RH.INCLUSIVE OF THE REPAIR OF FENDER RHR DJ/DL.		2,640.00	660.00
	TO RESPRAY REAR FENDER RH AND REAR DOOR RH.		1,890.00	1,360.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	NOT NECESSARY	180.00	-
	TO TRANSFER THE DOOR MECHANISM.	NOT NECESSARY	330.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		200.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NOT NECESSARY	250.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOU)	NOT NECESSARY	150.00	-
			5,640.00	2,140.00
	<b>GRAND TOTAL</b>		<b>7,151.00</b>	<b>2,174.70</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,174.70</b>

Report Ref No. CS/SMR21008698/Uuf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.