



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                         |  |  |                            |            |
|---|--|--|----------------------------|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705 |  |  | Ref: CS/SMR21008698/Uuf3n2 |            |
|   |  |  | Date: 01/12/2021           |            |
|   |  |  | Code: SMR                  |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |  |                            |            |
|   | Insured Veh.   | SMB 315C   | Veh. Inspected             | SLL 5584T  |
|   | Policy No.   |  | Coverage (\$)              | 0.00       |
|   | Claim No.  | BUS/08/21/5024   | Excess (\$)                | 0.00       |
|   | Assign From  | HUA YEN  | Assign Date                | 19/08/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |  |                            |            |
|   | Make & Model   | MAZDA 2 (A)  | c.c                        | 1496       |
|   | Engine No.   | HIDDEN   | Year of Reg.               | 2017       |
|   | Chassis No.  | MM6DL2SAAGW213890  | Colour                     | BROWN      |
|   | Odometer   | 84762 KM   | Steering                   | IN ORDER   |
|   | Brakes   | IN ORDER   | Modification               | SPORTS RIM |
|   | General  | GOOD   |                            |            |
| <b>3. Conditions of Tyres</b>   |  |  |                            |            |
|   |  | Size   | Make                       | Balance    |
|   | R/H Front Tyre   | 185/60 R16   | YOKOHAMA                   | 7 mm       |
|   | L/H Front Tyre   | 185/60 R16   | YOKOHAMA                   | 7 mm       |
|   | R/H Rear Tyre  | 185/60 R16   | YOKOHAMA                   | 7 mm       |
|   | L/H Rear Tyre  | 185/60 R16   | YOKOHAMA                   | 7 mm       |
| <b>4. Description of Damages</b>  |  |  |                            |            |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |                            |            |
| <b>5. General Information</b>   |  |  |                            |            |
|   | Accident Date  | 18/08/2021   | Inspection Date            | 20/10/2021 |
|   | Survey held at   | TRANS EUROKARS PTE LTD<br>NO 5 UBI CLOSE<br>SINGAPORE 408605 |                            |            |
| <b>5a. Remarks</b>  |  |  |                            |            |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                            |            |
| <b>5b. Estimate Days of Repair</b>  |  |  |                            |            |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | <b>3 Working Days</b>      |            |