

## **LKK Auto Consultants Pte Ltd**

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 7276R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT CORNER PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	438.00	-
1	FRT BLINKER LAMP LH (CONSISTENT)	CRACKED	229.00	209.00
1	HEADLAMP LH (CONSISTENT)	MTG CRACKED	669.00	619.00
1	FRT SIDE LAMP LH (CONSISTENT)	CRACKED	153.00	153.00
1	FRT BUMPER (CONSISTENT)	BUCKLED	880.00	833.00
1	FRT BUMPER BRACKET LH (CONSISTENT)	TO REPAIR SEE LABOUR	79.00	-
1	FRT WING MIRROR LH (CONSISTENT)	DENTED	98.00	98.00
1	FRT VIEW MIRROR (ROUND) (CONSISTENT)	SERVICEABLE	75.00	-
1	FRT MIRROR SUPPORT LH (CONSISTENT)	BENT	324.00	304.00
1	STEP GARNISH LH (CONSISTENT)	DENTED / CUT	235.00	235.00
	LESS 10% DISCOUNT		-318.00	-
	LESS 25% DISCOUNT		-	-612.75
			2,862.00	1,838.25
	SPECIAL NETT ITEMS			
1	FRT DOOR CO'S STICKER LH (SN) (CONSISTENT)	NECESSARY	25.00	25.00
			25.00	25.00
	<u>LABOUR</u>			
	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS.		80.00	20.00
	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT CORNER PANEL LH AND FRT BUMPER BRACKET LH.		400.00	300.00
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS.		500.00	400.00
			980.00	720.00
	GRAND TOTAL		3,867.00	2,583.25



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/ASM21008700/Kqce2

KONG SENG CHEONG

**Licensed Appraiser**