

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21008711/UPA3Q2
Date: 07/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0001455_02
Claimant Vehicle No :	SJS2409Z	Insured Vehicle No :	GM8458J
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0003599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS2409Z		
Make & Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Engine No:	HR15156991B
Reg. Date:	05/08/2009 (Man. Year: 2009)	Chassis No:	JN1BAAG11Z0110130
Colour:	Blue	Odometer:	371724 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,975.80	2,233.58	4,742.22	67.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	2,050.00	1,100.00	34.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,125.80	4,283.58	5,842.22	57.70
Approved Total (Overridden) (S\$)		3,400.00		

Nett Amount (S\$)	10,125.80	3,400.00	6,725.80	66.42
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,647.45		

INSPECTION

Date of Assignment: 19/08/2021

Date Inspected: 19/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2021)
Parts:	143	NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2409Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	980.70 F	*- FL
2	1		*BOOTLID REAR LOGO	Necessary	58.00 F	*45.00 FL
3	1		*BOOTLID SYLPHY EMBLEM	Necessary	62.00 F	*58.00 FL
4	1		*BOOTLID REFLECTOR O/S	Not Necessary	195.00 F	*- FL
5	1		*BOOTLID INNER LOCK	Not Necessary	166.80 F	*- FL
6	1		*BOOTLID WEATHERSTRIP	Not Necessary	185.50 F	*- FL
7	1		*BOOTLID LOWER CHROME	Not Necessary	245.00 F	*- FL
8	1		*BOOTLID UPPER CHROME	Not Necessary	311.90 F	*- FL
9	1		*REAR BUMPER	Deformed / Torn	845.20 F	*807.30 FL
10	1		*REAR BUMPER CHROME MOULDING	Necessary	244.50 F	*200.40 FL
11	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	70.00 F	*35.00 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*35.00 FL
13	2		*REAR BUMPER DAMPERS	Not Necessary	210.00 F	*- FL
14	1		*REAR BUMPER REFLECTORS	O/S Cracked	136.00 F	*48.50 FL
15	1		*REAR BUMPER SPONGE	Not Necessary	68.00 F	*- FL
16	1		*REAR END PANEL	Dented	515.00 F	*482.60 FL
17	1		*TAILLAMP O/S	Cracked	286.90 F	*259.10 FL
18	1		*REAR FENDER LOWER PANEL O/S	Badly Dented / Buckled	655.10 F	*455.30 FL
19	1		*REAR FENDER O/S	Repair	1,197.20 F	*- FL
20	1		*REAR AIR VENT O/S	Not Necessary	68.00 F	*- FL
21	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
22	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
23	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
24	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)

6,975.80

2,476.20

- List Item Discount on L Items 0.00/10.00% (\$\$)

0.00

242.62

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$\$)	6,975.80
						2,233.58
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	50.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	850.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			3,150.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >