

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008715/APA3Q2
Date: 01/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900243775
Claimant Vehicle No :	SME5945K	Insured Vehicle No :	SMF5863H
Date of Loss:	18/08/2021	Nature of Claim:	TP
		Claim No:	3379669989SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME5945K	Engine No:	16675176B48B20A
Make & Model:	BMW 520I LED NAV, 2.0 (A)	Chassis No:	WBAJA12060WC08997
Reg. Date:	15/02/2018 (Man. Year: 2017)	Odometer:	43481 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/30 R20	Rear Tyre Size:	285/30 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,990.00	3,764.10	225.90	5.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	990.00	360.00	26.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,340.00	4,754.10	585.90	10.97
Approved Total (Overridden) (S\$)		3,800.00		

(S\$)	5,340.00	3,800.00	1,540.00	28.84
+ GST 7.00/7.00% (S\$)	373.80	266.00	107.80	28.84
Nett Amount (S\$)	5,713.80	4,066.00	1,647.80	28.84
+ Car Rental (3.5 x S\$100.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,418.00		
Global Sum Settlement (S\$)		4,370.00		

INSPECTION

Date of Assignment: 19/08/2021

Date Inspected: 19/08/2021

Estimated Period of Repair: 3.0 days

 Inspected At: Modern Automotive Pte Ltd (HQ)
 Blk 3023A Ubi Road 1, #01-61 & #01-58
 Singapore 408717
Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,628.00 FL	*1,628.00 FL
2	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	136.00 FL	*136.00 FL
3	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	198.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	863.00 FL	*863.00 FL
5	1		*REAR BUMPER REINFORCEMENT COVER	Cracked	285.00 FL	*285.00 FL
6	1		*REAR BUMPER CENTRE GUIDE	Cracked	165.00 FL	*165.00 FL
7	1		*REAR BUMPER CENTRE GARNISH STRIP	Cracked	117.00 FL	*117.00 FL
8	1		*REAR BUMPER TOW COVER	Not Necessary	53.00 FL	*- FL
9	1		*REAR BUMPER UNDERCOVER	Torn	355.00 FL	*355.00 FL
10	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
11	2		*REVERSE SENSOR	Damaged	500.00 FS	*500.00 FS
12	1		*SET REAR BUMPER UNDERCOVER CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,370.00	4,119.00
- List Item Discount on L Items 10.00/10.00% (\$)	380.00	354.90
Total Parts (\$)	3,990.00	3,764.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	500.00	400.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	500.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO PERFORM DIAGNOSTIC TEST	New	200.00	100.00
Gross Labour Cost (S\$)			1,350.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >