# **LKK Auto Consultants** #01-25 Paya Ubi Industrial Park, 51 **Ubi Avenue 1** 408933

Insurer Reference: DM21H001209-JG

Repairer Reference:

**Registration: GBK6177C** Date calculated: 10/11/2021 5:14 PM Printed: 10/11/2021 5:14 PM

## **Summary Information**

Claim

Location: Work Provider: EQ Insurance Pte Ltd Singapore (SG)

Currency: Printed by: KK LAU **SGD** Claim Reference: DM21HO01209-JG Date of Incident: 19/08/21

Estimated Repair Time: Hire Car Start: Hire Car End: Actual Repair Days:

## **Vehicle Details**

Vehicle

Manufacturer: SUZUKI Model: **EVERY** Sub Model: BASE MODEL Model Sheet Number: 50 EY 01 Registration: GBK6177C

VIN number: Odometer:

**Full Report** 


## **Vehicle Condition**

**Vehicle Status** 

Pre-Accident Damage:

Date of Inspection: 20/08/21

**Damage Areas** 



## **Tyres Condition**

Tyre Brand Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Outer),

Condition

mm

mm

mm

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

#### Labour

|           | Time Base 10 WU/h   | Price = 60  | .00 SGD/h |
|-----------|---|-------------|-----------|
| Code      | Description   | WU          | Price SGD |
| NA02R0)   | R + R REAR BUMPER   | 4.0         | 24.00     |
| NO NUMBER | RENEW REAR BUMPER<br>(REMOVED)<br>INCLUDES: R + R NUMBER PLATE AND NUMBER<br>PLATE LAMP | 1.0         | 6.00      |
| 1018      | DISM/REFIX W/S GLASS LABOUR   | 20.0*       | 120.00    |
| 1020      | REVERSE SENSOR REAR   | 10.0*       | 60.00     |
| 1021      | RR EXHAUST PIPE REPAIR  | 10.0*       | 60.00     |
| 1022      | DAMAGED PORTION DISM/REWIRE   | 5.0*        | 30.00     |
| 1023      | PANEL BEAT DMG AREA RENEW PARTS   | 160.0*      | 960.00    |
|           | Labour Cost   | Hrs WU      |           |
|           | Panel / Mechanical Labour   | 21.00 210.0 | 1,260.00  |
|           | Total of Labour   |             | 1,260.00  |

## **Paint**

| Paint Work SYSTEM AZT |                                | Time Basis 10 WU/h |
|-----------------------|--------------------------------|--------------------|
| Code                  | Description                    | WU Price SGD       |
|                       | REAR BUMPER NEW PART PAINT K1G | 150.0*             |
|                       | SPRAY UNDERCOATING REPAIR      | 10.0*              |

#### **Paint Material Per Part**

| Code | Description                    | Price SGD |
|------|--------------------------------|-----------|
| 2583 | REAR BUMPER NEW PART PAINT K1G | 25.50     |

| Labour Cost - Paint |             | Hrs   | WU    | <b>Price SGD</b> |
|---------------------|-------------|-------|-------|------------------|
| Factor              | 60.00 SGD/h |       |       |                  |
| Time Paint          |             |       | 160.0 |                  |
| Total               | 10 WU/h     | 16.00 | 160.0 | 960.00           |

Material Cost - PaintPrice SGDNew Part Painting - Plastic K1G25.50Material-constant Plastic16.20Total41.70

## **Spare Parts**

|                                   |                        |               |             | prices as at 2015-06-01 |
|-----------------------------------|------------------------|---------------|-------------|-------------------------|
| Code                              | Description            | Part Number   | Part Source | Price SGD               |
| 2583                              | REAR BUMPER            | 7181168H00R7E | Original    | 625.00                  |
| 2618                              | R/R BUMPER BRACKET     | 7181368H00000 | Original    | 117.60                  |
| 1000                              | WINDSCREEN<br>MOULDING | REAR TAILGATE | Original    | 90.70                   |
| 1001                              | RR TAILGATE PANEL      | REAR TAILGATE | Original    | 899.60                  |
| 1003                              | LOCK ASSY              | REAR TAILGATE | Original    | 215.30                  |
| 1004                              | WEATHERSTRIP           | REAR TAILGATE | Original    | 293.40                  |
| 1005                              | SUZUKI LOGO            | REAR TAILGATE | Original    | 38.00                   |
| 1006                              | EVERY EMBLEM           | REAR TAILGATE | Original    | 35.00                   |
| 1007                              | INNER TRIM BOARD       | REAR TAILGATE | Original    | 224.60                  |
| 1008                              | RR BPR SIDE RETAINER   | 2PCS          | Original    | 124.60                  |
| 1009                              | R/BPR SIDE REFLECTOR   | 2PCS          | Original    | 465.00                  |
| 1010                              | RR FLOOR OUTER PANEL   | REAR          | Original    | 445.70                  |
| 1011                              | RR PANEL AIR DUCT      | 0/S           | Original    | 134.60                  |
| 1012                              | HOLDING ASSY           | RR SPARE TYRE | Original    | 195.00                  |
| C. OEM Davida                     | <b>6</b> .             |               |             |                         |
| f: OEM Parts                      | Savings                |               |             | 0.00                    |
| n: Non-OEM Parts<br>u: Used parts | Subtotal               | 4 = 000()     |             | 3,904.10                |
| u. Oseu parts                     | Subtotal Discount(+    | 15.00%)       |             | -585.62                 |
|                                   | Total                  |               |             | 3,318.48                |

## **Extras**

| Code | Description                  | Price SGD |
|------|------------------------------|-----------|
| 1013 | 70KM/H STICKER REAR          | 15.00*    |
| 1014 | 5 PAX STICKER REAR           | 15.00*    |
| 1015 | REVERSE SENSOR REAR          | 200.00*   |
| 1016 | DAM RUBBER REAR WINDSCREEN   | 60.00*    |
| 1017 | RR NUMBER PLATE NUMBER PLATE | 50.00*    |
|      | Total Extras                 | 340.00    |

## **Final Calculation**

|                                    | SGD       | SGD       |
|------------------------------------|-----------|-----------|
| Parts                              | 3,904.10  |           |
| Total Discount(+15.00%)            | -585.62   |           |
| Total Parts                        |           | 3,318.48  |
| Labour Time Base 10 WU/h           |           |           |
| Total 210.0 WU X 60.00 SGD/h       | 1,260.00  |           |
| Total of Labour                    |           | 1,260.00  |
| Total Of Extras                    |           | 340.00    |
| Paint Work Time Base 10 WU/h       |           |           |
| Labour Cost 160.0 WU X 60.00 SGD/h | 960.00    |           |
| Material Cost                      | 41.70     |           |
| Total Paint Including Material     |           | 1,001.70  |
| Repair Cost                        |           | 5,920.18  |
| Deductions (Excludes GST)          |           |           |
| Repair Cost Discount (+20.00%)     | -1,184.04 |           |
| Total Of Deductions (Excludes GST) | •         | -1,184.04 |
| Grand Total Excludes GST           |           | 4,736.14  |
| GST ()                             |           |           |

**Grand Total Included GST** 

## Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS

## **Assessment Note**

No assessment notes entered.